



Connection offline

Vehicle-specific service

Topic	91 PSS MMI sound: Settings for surround sound via head restraints are missing
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2077615/1
Level	EH
Status	Released for publishing
Release date	Apr 14, 2025

Vehicle data

Q6 with headrest speakers

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
GF*	2025	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
*	*	GF	*	S	*	000001	999999		

PR numbers

PR numbers
?:with 8RT

Documents

Document name
master.xml

Condition

Customer states:

The buttons for surround sound in the driver and passenger head rests are missing in the MMI sound settings; two unmarked bars (Figure 1) are shown instead. Operating these bars does not affect the sound settings.



Figure 1. Two unmarked bars are shown instead of buttons for surround sound in the head rests.

The concern occurs sporadically. The buttons for surround sound may be displayed again after a bus sleep cycle.

Workshop findings:

The concern can be reproduced in the workshop.

Technical Background

Software issue.

Production Solution

The concern will no longer occur in vehicles manufactured in week 48/25 or later.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 3rd quarter of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

If the complaint is made, it can possibly be remedied by performing a soft reset (pressing and holding the volume control) or a bus sleep cycle.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2077615**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©**2025 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.