

Reference	SSM76316
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	Floor Console Cool Box Inoperative
Category	Body
Last modified	25-Apr-2025 00:00:00
Symptom	107000 Interior Trim

Content **Model / Model Year / Derivative**

Range Rover / 22MY Onwards / Floor Console Cool Box
Range Rover Sport / 23MY Onwards / Floor Console Cool Box

Situation:

JLR Engineering investigations have identified customer reports of the floor console cool box is not working or no switch illumination. In some reports, with DTC B160D-87 - 'Cooled Centre Fridge Storage - Missing Message'

Action:

Refer to the service information below.

Service Information:

1. Confirm the customer symptom and complete the following TOPIx test plan: 'Floor Console Cool Box – Inoperative – Test'

(Ref 000371230 / 1061)

anBhdHRicnlM7MjAyNS0wNC0yNVQxND01NzoyNy4wODhaOzE2NS4yMjUuMzguMjUyOw==