

REVERSE CAMERA GRID LINES MISSING AFTER IPMB UPDATE

Concern

- Customer concern *"Ever since update of camera module, grid lines showing vehicle path are no longer seen in reverse camera display"*

Technical Description

- An incorrect Car Configuration File change is introduced during IPMB Camera Module software update.
- This CCF change affects the display of the grid lines normally seen in the reverse camera image display.

Action

1. Do Not replace the IPMB module for this concern as this will not correct the issue.
2. Reference **SSM76319** (LR) and **SSM76320** (Jaguar) and follow instructions outlined to submit a Technical Assistance case to amend the CCF to restore grid line function.
3. Instructions to complete update of vehicle with the corrected CCF will be provided through the Technical Assistance case.

Range Rover

- 17-22MY Range Rover
- 17-22MY RR Sport

Discovery

- 17-20MY Discovery

Jaguar

- 19-20MY I-PACE

JLR

