

GPOP - Issue Review System

Part Number: 68707382A\$, 68707383A\$, 68707384A\$, 68707385A\$, 68707387A\$,
68707388A\$

Part Description: Switch - Power Window

Issue Description: Before replacing the Window Switches (Termination AB Only), please follow these steps:
1.- Make sure all the switches are properly connected, disconnect the switch and reconnect it. 2.- In case the passenger/rear window switches are not working please, cycle the Door lock/Unlock Switches of the respective Switch (Lock and Unlock the doors at least 3 times) and try to roll the windows up and down. 3.- Check for what DTC are detected and take proper steps to diagnose the DTC's. if there are no DTC's then window switches can't be replaced.