

 Preview Solution CBR-901-5

Remote Control Central Door Lock, Programming; Key Fob Cannot Be Programmed Or Does Not Work After Programming - Model Year 2018 And Newer

Published 13 May 2025

Valid For

Mack Chassis - AN,GR,GU,MRU,TE,TD,LR,LEU,CHU,CXU,PI

Volvo Chassis - VN,VAH,VHD

Model Year 2018 to current

Issue

If the key fob fails to program successfully, it indicates a potential malfunction within the Central Locking Kit.

Resolution

1. Replacement of Central Locking Kit

- Install a new Central Locking Kit.
- Refer to **Impact Function Group 364** to identify the correct part number for the replacement **Central Locking Kit (Module and 2 fobs)**.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article