

Field campaign

Topic	Software Update BiL 5.3.1 v1 to v2 Continental GT/GTC 25MY (SC25/09)
Market area	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
Brand	Bentley
Transaction No.	2077315/7
Campaign number	ED39
Note	
Type	
US code	

Vehicle data

25MY Continental GT & GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
Z23*	2025	E		*	*	*
Z24*	2025	E		*	*	*

Documents

Document name
master.xml
ed39_svm_code.pdf
ed39vinlist.pdf

.....

Notes



Technical background

Software updates must be applied to update the vehicles Baseline.

The software update corrects the following Diagnostic trouble codes:

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error
- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).

Remedy

The instructions within the 'Work' section **must** be conducted to completion.

Customer notification

Please ensure all applicable instructions are conducted at the nearest opportunity.

Warranty

SVM Update Time

Claim type: 790 or 710

Service number: ED39

Damage code: 0066

Criteria:01

Labour Operation Code: 01 51 00 00

Time: As per ODIS log (Must not exceed 100TU)

Parts

Not Applicable

Parts supply

Not Applicable

Parts despatch control

Not Applicable

Repair instructions



Technical background

Software updates must be applied to update the vehicles Baseline.

The software update corrects the following Diagnostic trouble codes:

- P060100: High Voltage Battery (Address 008C) Internal Control Module Memory Checksum Error
- P057F00: Battery "A" State of Charge Performance, B11B300 Igniter for high voltage battery interrupt
- P0A0B00: High Voltage System Interlock Circuit Performance (HVIL).

Check

Check if the vehicle is already listed as repaired in "Repair history" (in ElsaPro).

Please also refer to the "Identification" section and check if a paint identification mark is evident in the vehicle.

If the vehicle is not shown in ElsaPro as repaired, and the identification mark is not present, please conduct the instructions within the 'Work' section to completion

Parts

Not Applicable

Work

CAUTION

The Bentley ODIS-S Brand Version **MUST** be at least 2.35.1 (or higher)

CAUTION

Before conducting the onward instructions, the operative **MUST** recheck the communication method in ODIS and ensure that DoIP is selected before proceeding. Within ODIS-S, perform the following:

- On the right hand side, select the “Admin” tile (Within ‘Operating modes’)
- Select “GFF sequence” (Within ‘General information’ section)
- Under the “Selection of Communication path” drop-down menu, select “Only permit DoIP communication”.

CAUTION

DO NOT, UNDER ANY CIRCUMSTANCES, ATTEMPT TO CONDUCT THE SOFTWARE UPDATE VIA THE CAN NETWORK. ONLY DoIP SHOULD BE USED WHEN PERFORMING THE SVM UPDATE.

CAUTION

You **MUST ONLY** use the Diagnosis Interface VAS 6154 (WiFi Diagnostic Tool) in USB OPERATION or the CABLE-CONNECTED VAS 5055 for the reprogramming (updating) of the control units.

- If neither of these units are available, the VAS 5054 (A) may be used in USB MODE.
- **DO NOT** under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control units.

Battery Charger

CAUTION

ONLY Chargers that meet the approved specification on the Mandatory Equipment List (available on the Bentley Hub) **MUST** be used.

- The charger must be set to a mode where a **MINIMUM** of 90a is supplied to the battery during the process. Typically, this is known as ‘Power Supply Mode’ or ‘DIAG+ Mode’.
- A voltage of exactly 14.8v must be set and maintained throughout the process.
- Please refer to the manual to ensure that these requirements are met before beginning any SVM update

Preparation Before Update

WARNING


Hybrid Vehicles use a High Voltage System and therefore **MUST ONLY** be worked on by suitable personnel

CAUTION

During the update, switch off all unnecessary consumers. For example, ventilation, seat heaters, interior illumination, exterior lights ect.

Conduct a full guided fault find of the vehicle.

If a ‘Check Installation List’ pop-up appears, select ‘close’ (see below image)



Referring to TPI 2075920, address any unknown faults **BEFORE** conducting any of the below updates.

Ensure that the correct battery charge is connected to the vehicle. – Refer to the “Battery Charger” Section above.

Obtaining Hotfix for ODIS-S


Visit <https://bentley.atheer.io/> and log in with the following case-sensitive account details.

- Username: bilupdate
- Password: Bentley123!


NOTICE

If you are already logged into your retailer account, you will need to logout first. To do this, click on your account initials (bottom left corner) and click “Sign Out”.

After logging in, using the navigation bar on the left hand side, click on the ‘conversations’ tab



Next, click the conversation named “ED37/ED39 Hotfix Download”



In this conversation, you will find a file named “ED37_ED39_Hotfix”. Left click the file name and download the file.

After left-clicking the files to download them, the download will take circa 5-10 minutes, do not interrupt this process. You may need to wait a short period (internet speed dependent) for the files to download.

During/before the download commences, there may be a warning about a “pop-up” being blocked which will prevent the file from downloading, ensure to select option “Allow Pop-Ups from this website” to download the file. Wording may differ depending on web browser.

Locate the download file and extract it. To do this, right click the file, click “7 zip” and then “Extract here”

After successfully downloading the file, please logout of the account.

Loading ODIS-S Hotfix

With the hotfix you have downloaded from Atheer, load the hotfix into ODIS-S. The Bentley ODIS-S Brand Version **MUST** be at least 2.35.1 (or higher).

Obtaining Correct SVM Code

Due to the intricacies behind Bentley Integration Levels (BiL), you must identify which SVM code each VIN requires.

Please find the applicable VIN on the attached "ed39_svm_code" document.

Note down the associated SVM code from the SVM Code column.

Keep note of this SVM code as you will be required to enter this into ODIS-S, later on in the procedure.

First SVM Code Input

CAUTION

At this point, a suitable battery charger must be connected to the vehicle.

1. In ODIS-S, navigate to the "Special Functions" tab.
2. Navigate to 'SVM – Code Input' and enter the SVM code which you have obtained from the attached "ed39_svm_code" pdf.
3. On the next screen, ensure that the SVM code displayed is correct.
4. You will be shown the communication type. **This MUST be set to "DoIP"**.
 - a. If "DoIP" is not selected, select option 3 until the communication type is set to "DoIP".
5. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – "Yes".
 - a. From here, all control modules will be interrogated and the SVM action will take place.
6. Ensure that the diagnostic device remains connected for the duration of the update.
7. Follow all on-screen prompts until the program ends.
 - a. If you have a prompt stating there is no communication established with 00CC, select done/continue.
8. Follow the on-screen instructions to completion.

NOTICE

If you receive an error code: 8088, you must follow the below instructions.

1. In ODIS-S, navigate to the "Special Functions" tab.
2. Navigate to 'SVM – Code Input' and enter the SVM code: "372A5CONFIG01"
3. On the next screen, ensure that the SVM code displayed is correct.
4. You will be shown the communication type. **This MUST be set to "DoIP"**.
 - a. If "DoIP" is not selected, select option 3 until the communication type is set to "DoIP".
5. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – "Yes".
 - a. From here, all control modules will be interrogated and the SVM action will take place.
6. Ensure that the diagnostic device remains connected for the duration of the update.

7. Follow all on-screen prompts until the program ends.
 - a. If you have a prompt stating there is no communication established with 00CC, select done/continue.
8. You may or may not encounter an error after the update.
9. Refer back to the start of "First SVM Code Input" and repeat the process to input the SVM code obtained from the attached document "ed39_svm_code".
10. Perform a whole vehicle DTC clear by exiting the current diagnostic session.
11. Perform a 15 minute CAN bus sleep.
 - a. Turn off the ignition.
 - b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
 - c. Close all doors, windows, bonnet and boot lid.
 - d. Lock the vehicle to perform a CAN-BUS sleep (wait 15 minutes).
12. Re-run guided fault finding and clear DTCs

High Voltage Shutdown



WARNING

De-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – "De-energising high-voltage system" to do so.

Second SVM Code Input

1. Navigate to 'SVM – Code Input'
 - a. If the vehicle is any variant of a Continental GT or GTC, enter the SVM Code: "372HVBJB01".
 - b. If the vehicle is any variant of a Continental Flying Spur, enter the SVM Code: "373HVBJB01".
2. On the next screen, ensure that the SVM code displayed is correct.
3. You will be shown the communication type. **This MUST be set to "DoIP"**.
 - a. If "DoIP" is not selected, select option 3 until the communication type is set to "DoIP".
4. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – "Yes".
 - a. From here, all control modules will be interrogated and the SVM action will take place.
5. Ensure that the diagnostic device remains connected for the duration of the update.
6. Follow all on-screen prompts until the program ends.
 - a. If you have a prompt stating there is no communication established with 00CC, select done/continue.
7. Follow the on-screen instructions to completion.



NOTICE

Flashing of the control module 06D0 may fail due to pre-conditions not being met. (Fig 1)
– Please follow the steps below if you encounter this problem.




Fig 1

1. Press "Done/Continue" and then on the next screen, select Option 3: 'Cancel test programme'.
2. Perform a 15 minute CAN bus sleep.
 - a. Turn off the ignition.
 - b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
 - c. Close all doors, windows, bonnet and boot lid.
 - d. Lock the vehicle to perform a CAN-BUS sleep (wait 15 minutes).
3. Perform a whole vehicle DTC clear by exiting the current diagnostic session. Then, re-run guided fault finding.
4. Navigate to 'SVM – Code Input'
 - a. If the vehicle is any variant of a Continental GT or GTC, enter the SVM Code: "372HVBJB01".
 - b. If the vehicle is any variant of a Continental Flying Spur, enter the SVM Code: "373HVBJB01".
5. On the next screen, ensure that the SVM code displayed is correct.
6. You will be shown the communication type. **This MUST be set to "DoIP"**.
 - a. If "DoIP" is not selected, select option 3 until the communication type is set to "DoIP".
7. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – "Yes".
 - a. From here, all control modules will be interrogated and the SVM action will take place.
8. Ensure that the diagnostic device remains connected for the duration of the update.
9. This error message may or may not appear (Fig 2) on the ODIS-S terminal. Regardless of if the error message appears, continue with the next steps.

Action: Report



Issue relating to back documentation

The following SVM error occurred: **ERPUNCEX8135**

The SVM Process will now exit.

- Press the Complete/Continue button to continue.

Fig 2

Third SVM Code Input

WARNING

Re-energise the high-voltage system via ODIS-S. Refer to ElsaPro, Repair Group 93 – “Re-energising high-voltage system” to do so.

1. After re-energising the High Voltage System, navigate to the “Special Functions” tab in ODIS-S.
2. Navigate to ‘SVM – Code Input’
 - a. If the vehicle is any variant of a Continental GT or GTC, enter the SVM Code: “372531COM01”.
 - b. If the vehicle is any variant of a Continental Flying Spur, enter the SVM Code: “373531COM02”.
3. On the next screen, ensure that the SVM code displayed is correct.
4. You will be shown the communication type. **This MUST be set to “DoIP”.**
 - a. If “DoIP” is not selected, select option 3 until the communication type is set to “DoIP”.
5. After ensuring DoIP is selected, and a suitable battery charger is connected, select Option 1 – “Yes”.
 - a. From here, all control modules will be interrogated and the SVM action will take place.
6. Ensure that the diagnostic device remains connected for the duration of the update.
7. Follow all on-screen prompts until the program ends.
 - a. If you have a prompt stating there is no communication established with 00CC, select done/continue.
8. Follow the on-screen instructions to completion.
9. If you are presented with this screen (Fig 3) at the end of the update, the update was successful. Please continue to step 11.




Fig 3

10. If you encounter any errors during the update, please raise a FULL TECHNICAL DISS query.
 - a. Customer Statement: “ED39 Support”
 - b. Workshop Findings: Give a summary of the error encountered and ensure that the GFF log is submitted online.
11. After successful completion of the update, perform the following.

- a. Turn off the ignition.
- b. Remove all equipment from the car (Diagnostic tester/dongle, battery charger, keys).
- c. Close all doors, windows, bonnet and boot lid.
- d. Lock the vehicle to perform a CAN-BUS sleep (wait 10 minutes).

12. After 30 minutes, unlock and open the driver's door. Turn on the ignition, re-connect the battery charger and diagnostic dongle.

13. Re-run guided fault finding and clear DTCs. If any faults are present, refer to TPI 2075920. If any other faults are present are non-sporadic, please raise a full DISS query with a full GFF log uploaded online stating the error encountered.

Identification

Once the applicable action has been conducted, the operative must submit a warranty claim as this will show the service campaign action as complete within Elsa Pro "Repair history".

You must also add a blue paint mark as per the picture below.



VIN	SVM Code
SCBCF13S8SC020919	372531ED3901
SCBCR2ZG2SC021256	372531ED3901
SCBCF13S7SC021267	372531ED3901
SCBDR4ZG5SC021266	372531ED3901
SCBDR4ZG9SC021254	372531ED3901
SCBCF13S0SC021255	372531ED3901
SCBCF13S1SC021264	372531ED3901
SCBCF13S8SC021259	372531ED3901
SCBCR2ZG3SC021279	372531ED3901
SCBDF33S5SC021252	372531ED3901
SCBDF33S8SC021276	372531ED3901
SCBDR4ZG4SC021260	372531ED3901
SCBDR4ZG7SC021270	372531ED3901
SCBDR4ZGXSC021294	372531ED3901
SCBCF13S4SC021274	372531ED3901
SCBCF13S7SC021320	372531ED3901
SCBCF13S8SC021262	372531ED3901
SCBCJ13S0SC021304	372531ED3901
SCBCJ13S1SC021313	372531ED3901
SCBCJ13S8SC021308	372531ED3901
SCBDF33SXSC021280	372531ED3901
SCBDR4ZG1SC021314	372531ED3901
SCBDR4ZG5SC021283	372531ED3901
SCBCF13S3SC021332	372531ED3901
SCBCF13S5SC021347	372531ED3901
SCBCJ13S4SC021340	372531ED3901
SCBCJ1ZG9SC021353	372531ED3901
SCBCR13S2SC021278	372531ED3901
SCBCR2ZG1SC021300	372531ED3901
SCBCR2ZGXSC021344	372531ED3901
SCBDF33S0SC021272	372531ED3901
SCBDF33S0SC021322	372531ED3901
SCBDF33SXSC021358	372531ED3901
SCBDR4ZG1SC021345	372531ED3901
SCBDR4ZG4SC021310	372531ED3901
SCBDR4ZG4SC021355	372531ED3901
SCBDR4ZG7SC021334	372531ED3901
SCBDR4ZG8SC021326	372531ED3901
SCBDR4ZGXSC021330	372531ED3901
SCBCF13S1SC021328	372531ED3901
SCBCF13S5SC021381	372531ED3901
SCBCJ13S8SC021390	372531ED3901
SCBCR13S4SC021363	372531ED3901
SCBCR2ZG0SC021370	372531ED3901

SCBCR2ZG3SC021377	372531ED3901
SCBDF33S6SC021342	372531ED3901
SCBDR4ZG2SC021287	372531ED3901
SCBDR4ZG4SC021338	372531ED3901
SCBDR4ZG5SC021302	372531ED3901
SCBDR4ZG7SC021348	372531ED3901
SCBCG13S9SC021350	372531ED3901
SCBCR2ZG5SC021414	372531ED3901
SCBDF33S2SC021306	372531ED3901
SCBDF33S4SC021291	372531ED3901
SCBDF33S9SC021318	372531ED3901
SCBDF33S9SC021352	372531ED3901
SCBDR4ZG0SC021384	372531ED3901
SCBDR4ZG6SC021258	372531ED3901
SCBCF13S3SC021430	372531ED3901
SCBCG13S1SC021309	372531ED3901
SCBCG13S5SC021393	372531ED3901
SCBCG13SXSC021406	372531ED3901
SCBCJ13S2SC021336	372531ED3901
SCBCJ13S8SC021339	372531ED3901
SCBCR13SXSC021383	372531ED3901
SCBDF33S0SC021398	372531ED3901
SCBDF33S2SC021368	372531ED3901
SCBDF33S5SC021428	372531ED3901
SCBDF33S7SC021365	372531ED3901
SCBDF33S9SC021416	372531ED3901
SCBDR4ZG1SC021362	372531ED3901
SCBDR4ZG7SC021379	372531ED3901
SCBDR4ZG8SC021424	372531ED3901
SCBCF13S1SC021460	372531ED3901
SCBCF13S4SC021470	372531ED3901
SCBCF13S7SC021396	372531ED3901
SCBCF1ZG9SC021418	372531ED3901
SCBCG13S8SC021324	372531ED3901
SCBCG13S8SC021467	372531ED3901
SCBCG13SXSC021356	372531ED3901
SCBCJ13S8SC021292	372531ED3901
SCBCR2ZG1SC021426	372531ED3901
SCBCR2ZG5SC021462	372531ED3901
SCBCR2ZG6SC021440	372531ED3901
SCBDR4ZG1SC021412	372531ED3901
SCBDR4ZG2SC021371	372531ED3901
SCBDR4ZG7SC021446	372531ED3901
SCBDR4ZGXSC021375	372531ED3901
SCBCF13S5SC021431	372531ED3901

SCBCF13S7SC021477	372531ED3901
SCBCF13S7SC021480	372531ED3901
SCBCG13S2SC021285	372531ED3901
SCBCG13S7SC021444	372531ED3901
SCBCG13S7SC021475	372531ED3901
SCBCR2ZG0SC021367	372531ED3901
SCBCR2ZG5SC021445	372531ED3901
SCBDF33SXSC021392	372531ED3901
SCBDR4ZG7SC021463	372531ED3901
SCBDR4ZG9SC021402	372531ED3901
SCBDR4ZGXSC021408	372531ED3901
SCBCF13S6SC021504	372531ED3901
SCBCF1ZGXSC021458	372531ED3901
SCBCR2ZG3SC021282	372531ED3901
SCBCR2ZG9SC021500	372531ED3901
SCBDF33S1SC021510	372531ED3901
SCBDR4ZG8SC021388	372531ED3901
SCBCF13S6SC021535	372531ED3901
SCBCF13S8SC021536	372531ED3901
SCBCG13S1SC021312	372531ED3901
SCBCG13S3SC021487	372531ED3901
SCBCG13S5SC021488	372531ED3901
SCBCG13S6SC021404	372531ED3901
SCBCJ1ZG7SC021531	372531ED3901
SCBCR2ZG2SC021516	372531ED3901
SCBCR2ZG3SC021508	372531ED3901
SCBCR2ZG7SC021558	372531ED3901
SCBDF33S3SC021489	372531ED3901
SCBDF3ZG1SC021476	372531ED3901
SCBDR4ZG1SC021524	372531ED3901
SCBDR4ZG6SC021468	372531ED3901
SCBCF13S3SC021539	372531ED3901
SCBCF13S4SC021565	372531ED3901
SCBCF13S6SC021289	372531ED3901
SCBCF13S7SC021575	372531ED3901
SCBCG13S2SC021268	372531ED3901
SCBCG13S4SC021501	372531ED3901
SCBCR2ZG2SC021497	372531ED3901
SCBCR2ZG3SC021556	372531ED3901
SCBCR2ZG5SC021512	372531ED3901
SCBCR2ZG8SC021360	372531ED3901
SCBDF33S7SC021513	372531ED3901
SCBDF33S8SC021567	372531ED3901
SCBDF33SXSC021554	372531ED3901
SCBDR4ZG0SC021532	372531ED3901

SCBDR4ZG1SC021569	372531ED3901
SCBDR4ZG2SC021547	372531ED3901
SCBDR4ZG3SC021542	372531ED3901
SCBDR4ZG3SC021573	372531ED3901
SCBDR4ZG5SC021560	372531ED3901
SCBDR4ZG6SC021471	372531ED3901
SCBDR4ZG9SC021450	372531ED3901
SCBCF13S0SC021546	372531ED3901
SCBCF13S1SC021605	372531ED3901
SCBCF13S4SC021582	372531ED3901
SCBCF13S5SC021607	372531ED3901
SCBCF13S8SC021570	372531ED3901
SCBCG13S2SC021562	372531ED3901
SCBCG13S6SC021595	372531ED3901
SCBCR2ZG9SC021433	372531ED3901
SCBDF33S6SC021597	372531ED3901
SCBDF33S8SC021522	372531ED3901
SCBDF33SXSC021585	372531ED3901
SCBDR4ZG0SC021482	372531ED3901
SCBDR4ZG0SC021577	372531ED3901
SCBDR4ZG6SC021552	372531ED3901
SCBCF13S3SC021587	372531ED3901
SCBCF13S5SC021624	372531ED3901
SCBCF13S8SC021634	372531ED3901
SCBCF13SXSC021490	372531ED3901
SCBCG13S8SC021615	372531ED3901
SCBCR13S1SC021627	372531ED3901
SCBCR2ZG7SC021642	372531ED3901
SCBDF33S0SC021580	372531ED3901
SCBDF33S3SC021654	372531ED3901
SCBDF33SXSC021540	372531ED3901
SCBDF33SXSC021604	372531ED3901
SCBDF33SXSC021635	372531ED3901
SCBDG33S3SC021442	372531ED3901
SCBDG33S4SC021496	372531ED3901
SCBDG33S7SC021394	372531ED3901
SCBDR4ZG1SC021538	372531ED3901
SCBDR4ZG4SC021419	372531ED3901
SCBDR4ZG4SC021601	372531ED3901
SCBCF13S4SC021646	372531ED3901
SCBCF13S5SC021610	372531ED3901
SCBCF13S7SC021589	372531ED3901
SCBCF1ZG8SC021457	372531ED3901
SCBCG13S4SC021420	372531ED3901
SCBCG13S6SC021578	372531ED3901

SCBCG13S8SC021386	372531ED3901
SCBCG13S8SC021436	372531ED3901
SCBCG13SXSC021373	372531ED3901
SCBCR2ZG0SC021644	372531ED3901
SCBCR2ZG0SC021661	372531ED3901
SCBCR2ZG2SC021662	372531ED3901
SCBDF33S2SC021564	372531ED3901
SCBDF33S4SC021629	372531ED3901
SCBDF33S9SC021612	372531ED3901
SCBDR4ZG9SC021626	372531ED3901
SCBCF13S2SC021614	372531ED3901
SCBCG13S0SC021527	372531ED3901
SCBCG13S8SC021520	372531ED3901
SCBCJ13S1SC021649	372531ED3901
SCBCR13S9SC021553	372531ED3901
SCBCR2ZG1SC021670	372531ED3901
SCBCR2ZG2SC021550	372531ED3901
SCBCR2ZG2SC021631	372531ED3901
SCBCR2ZG7SC021673	372531ED3901
SCBDF33S3SC021699	372531ED3901
SCBDF33S5SC021672	372531ED3901
SCBDF33S6SC021549	372531ED3901
SCBDF33SXSC021666	372531ED3901
SCBDR4ZG0SC021658	372531ED3901
SCBDR4ZG2SC021693	372531ED3901
SCBDR4ZG3SC021461	372531ED3901
SCBDR4ZG3SC021668	372531ED3901
SCBDR4ZG3SC021685	372531ED3901
SCBDR4ZG8SC021651	372531ED3901
SCBDR4ZG8SC021682	372531ED3901
SCBDR4ZG9SC021593	372531ED3901
SCBCF13S3SC021623	372531ED3901
SCBCF13S3SC021704	372531ED3901
SCBCF13S4SC021677	372531ED3901
SCBCF13S9SC021660	372531ED3901
SCBCF13S9SC021691	372531ED3901
SCBCF13SXSC021473	372531ED3901
SCBCG13SXSC021728	372531ED3901
SCBCR2ZG1SC021572	372531ED3901
SCBCR2ZG2SC021712	372531ED3901
SCBCR2ZG5SC021719	372531ED3901
SCBCR2ZG7SC021494	372531ED3901
SCBDR4ZG0SC021689	372531ED3901
SCBDR4ZG5SC021705	372531ED3901
SCBDR4ZG6SC021633	372531ED3901

SCBDR4ZG9SC021724	372531ED3901
SCBCF13S0SC021742	372531ED3901
SCBCF13S1SC021684	372531ED3901
SCBCF13S4SC021713	372531ED3901
SCBCF13S7SC021740	372531ED3901
SCBCF13SXSC021599	372531ED3901
SCBCF1ZG5SC021688	372531ED3901
SCBCG13S8SC021422	372531ED3901
SCBCG13S9SC021591	372531ED3901
SCBDF33S5SC021736	372531ED3901
SCBDR4ZG0SC021675	372531ED3901
SCBDR4ZG1SC021720	372531ED3901
SCBDR4ZG6SC021647	372531ED3901
SCBDR4ZG8SC021679	372531ED3901
SCBCF13S1SC021653	372531ED3901
SCBCF13S1SC021748	372531ED3901
SCBCF13S7SC021656	372531ED3901
SCBCF13S7SC021737	372531ED3901
SCBCF1ZG7SC021756	372531ED3901
SCBCG13S1SC021696	372531ED3901
SCBCR2ZG3SC021752	372531ED3901
SCBCR2ZG3SC021766	372531ED3901
SCBDF33S0SC021434	372531ED3901
SCBDF33S0SC021739	372531ED3901
SCBDF33S4SC021727	372531ED3901
SCBDR4ZG0SC021711	372531ED3901
SCBCF13S4SC021551	372531ED3901
SCBCF13S4SC021744	372531ED3901
SCBCF13S4SC021761	372531ED3901
SCBCF13S4SC021775	372531ED3901
SCBCF13S5SC021770	372531ED3901
SCBCF13S8SC021780	372531ED3901
SCBCF13S9SC021769	372531ED3901
SCBCF13S9SC021786	372531ED3901
SCBCG13S0SC021804	372531ED3901
SCBCG13S1SC021763	372531ED3901
SCBCG13S8SC021789	372531ED3901
SCBCG13SXSC021454	372531ED3901
SCBCG13SXSC021776	372531ED3901
SCBCJ13S2SC021790	372531ED3901
SCBCR2ZG8SC021410	372531ED3901
SCBDF33S6SC021714	372531ED3901
SCBDF33SXSC021750	372531ED3901
SCBDG33S6SC021502	372531ED3901
SCBDR4ZG4SC021730	372531ED3901

SCBDR4ZG5SC021753	372531ED3901
SCBDR4ZG7SC021771	372531ED3901
SCBDR4ZGXSC021747	372531ED3901
SCBCF13S2SC021810	372531ED3901
SCBCF13S5SC021638	372531ED3901
SCBCF13S7SC021723	372531ED3901
SCBCF13S7SC021754	372531ED3901
SCBCF13S8SC021617	372531ED3901
SCBCG13S1SC021830	372531ED3901
SCBCG13S8SC021825	372531ED3901
SCBCR2ZG1SC021801	372531ED3901
SCBCR2ZG5SC021798	372531ED3901
SCBDF33S5SC021820	372531ED3901
SCBDF33S8SC021794	372531ED3901
SCBDF33SXSC021764	372531ED3901
SCBDF33SXSC021778	372531ED3901
SCBDF33SXSC021800	372531ED3901
SCBDR4ZG2SC021743	372531ED3901
SCBDR4ZG2SC021760	372531ED3901
SCBDR4ZG5SC021784	372531ED3901
SCBDR4ZG7SC021530	372531ED3901
SCBDR4ZG9SC021643	372531ED3901
SCBCF13S0SC021840	372531ED3901
SCBCF13S4SC021856	372531ED3901
SCBCF13S9SC021822	372531ED3901
SCBCG13S0SC021818	372531ED3901
SCBCG13S7SC021850	372531ED3901
SCBCR2ZG8SC021665	372531ED3901
SCBCR2ZG8SC021827	372531ED3901
SCBCR2ZG9SC021707	372531ED3901
SCBDF33SXSC021781	372531ED3901
SCBDR4ZG3SC021797	372531ED3901
SCBCF13S5SC021817	372531ED3901
SCBCF13S5SC021834	372531ED3901
SCBCG13S0SC021866	372531ED3901
SCBCG13S1SC021861	372531ED3901
SCBCG13S5SC021832	372531ED3901
SCBCG13SXSC021759	372531ED3901
SCBCJ13S3SC021331	372531ED3901
SCBCR2ZG7SC021852	372531ED3901
SCBDF33S3SC021802	372531ED3901
SCBDF33S3SC021816	372531ED3901
SCBDF33S5SC021493	372531ED3901
SCBDR4ZG4SC021839	372531ED3901
SCBCF13S0SC021692	372531ED3901

SCBCF13S4SC021680	372531ED3901
SCBDR4ZG0SC021448	372531ED3901
SCBCF13S1SC021717	372531ED3901
SCBCF13S5SC021509	372531ED3901
SCBCG13S9SC021400	372531ED3901
SCBCR2ZG1SC021734	372531ED3901
SCBDG33S3SC021859	372531ED3901
SCBCF13S3SC021296	372531ED3901
SCBDF33S4SC021663	372531ED3901
SCBDF33S7SC021298	372531ED3901
SCBDG33SXSC021518	372531ED3901
SCBCF13S2SC021709	372531ED3901
SCBDF33S0SC021465	372531ED3901
SCBDF33S8SC021505	372531ED3901
SCBCF13SXSC021814	372531ED3901
SCBCH13S6SC021609	372531ED3901
SCBDR4ZG5SC021848	372531ED3901
SCBDF33S6SC021857	372531ED3901
SCBDJ33S7SC021767	372531ED3901
SCBDR4ZG9SC021805	372531ED3901
SCBCF13S5SC021879	372531ED3902
SCBCF13S7SC021849	372531ED3902
SCBCF13S8SC021875	372531ED3902
SCBCF1ZG8SC021796	372531ED3902
SCBCG13S1SC021813	372531ED3902
SCBCR2ZG8SC021858	372531ED3902
SCBDF33S1SC021829	372531ED3902
SCBDF33S7SC021835	372531ED3902
SCBDF33SXSC021845	372531ED3902
SCBDF3ZG5SC021867	372531ED3902
SCBDR4ZG2SC021757	372531ED3902
SCBCF13S0SC021806	372531ED3902
SCBCF13S0SC021885	372531ED3902
SCBCF13S4SC021890	372531ED3902
SCBCF13S6SC021891	372531ED3902
SCBCF13SXSC021733	372531ED3902
SCBCG13S0SC021883	372531ED3902
SCBCG13S4SC021773	372531ED3902
SCBCG13S5SC021846	372531ED3902
SCBCR2ZG6SC021583	372531ED3902
SCBCR2ZG7SC021821	372531ED3902
SCBCR2ZGXSC021876	372531ED3902
SCBDF33S0SC021823	372531ED3902
SCBDF33S4SC021808	372531ED3902
SCBDR4ZG2SC021788	372531ED3902

SCBDR4ZG2SC021841	372531ED3902
SCBDR4ZG3SC021864	372531ED3902
SCBDR4ZG5SC021901	372531ED3902
SCBCF13S0SC021868	372531ED3902
SCBCF13S3SC021928	372531ED3902
SCBCF13S6SC021910	372531ED3902
SCBCG13S4SC021837	372531ED3902
SCBCR2ZG0SC021921	372531ED3902
SCBCR2ZG1SC021927	372531ED3902
SCBCR2ZG4SC021906	372531ED3902
SCBCR2ZG6SC021700	372531ED3902
SCBCR2ZG6SC021809	372531ED3902
SCBCR2ZG8SC021889	372531ED3902
SCBDF33S0SC021899	372531ED3902
SCBDF33S2SC021919	372531ED3902
SCBDF33S3SC021881	372531ED3902
SCBDF33S8SC021438	372531ED3902
SCBDR4ZG1SC021877	372531ED3902
SCBDR4ZGXSC021831	372531ED3902
SCBCF13S2SC021905	372531ED3902
SCBCF13S3SC021931	372531ED3902
SCBCF13S8SC021942	372531ED3902
SCBCF13S9SC021920	372531ED3902
SCBCF1ZG8SC021894	372531ED3902
SCBCG13S3SC021909	372531ED3902
SCBCG13S7SC021783	372531ED3902
SCBCG13S8SC021940	372531ED3902
SCBCG13SXSC021843	372531ED3902
SCBCR2ZG6SC021874	372531ED3902
SCBCR2ZGXSC021912	372531ED3902
SCBCR2ZGXSC021957	372531ED3902
SCBDF33S0SC021935	372531ED3902
SCBDF33S3SC021895	372531ED3902
SCBDF33S5SC021932	372531ED3902
SCBDR4ZG0SC021854	372531ED3902
SCBCF13S1SC021961	372531ED3902
SCBCF13S7SC021785	372531ED3902
SCBCF13S7SC021978	372531ED3902
SCBCF13S8SC021844	372531ED3902
SCBCF13S9SC021965	372531ED3902
SCBCG13S0SC021950	372531ED3902
SCBCG13S2SC021934	372531ED3902
SCBCG13S5SC021958	372531ED3902
SCBCG13S6SC021984	372531ED3902
SCBCG13S7SC021945	372531ED3902

SCBCG13S7SC021976	372531ED3902
SCBCG13SXSC021938	372531ED3902
SCBCG13SXSC021969	372531ED3902
SCBCJ13S4SC021452	372531ED3902
SCBCR2ZG3SC021900	372531ED3902
SCBCR2ZG4SC021954	372531ED3902
SCBCR2ZG6SC021485	372531ED3902
SCBDF33S1SC021930	372531ED3902
SCBDF33S9SC021870	372531ED3902
SCBDR4ZG2SC021872	372531ED3902
SCBDR4ZG7SC021964	372531ED3902
SCBCF13S2SC021970	372531ED3902
SCBCF13S5SC022000	372531ED3902
SCBCG13S2SC021982	372531ED3902
SCBCG13S2SC022016	372531ED3902
SCBCG13S7SC021914	372531ED3902
SCBCR2ZG2SC022004	372531ED3902
SCBCR2ZG7SC022015	372531ED3902
SCBDF33S1SC021975	372531ED3902
SCBDF33S6SC021888	372531ED3902
SCBDF33S9SC021948	372531ED3902
SCBCF13S1SC022012	372531ED3902
SCBCF13S4SC021887	372531ED3902
SCBCF13S4SC022019	372531ED3902
SCBCF13S9SC022002	372531ED3902
SCBCF1ZG1SC021963	372531ED3902
SCBCF1ZG8SC022009	372531ED3902
SCBCG13S3SC021991	372531ED3902
SCBCR2ZG5SC021994	372531ED3902
SCBCR2ZG6SC021986	372531ED3902
SCBCR2ZG6SC022037	372531ED3902
SCBCR2ZG9SC022047	372531ED3902
SCBDF33S5SC022014	372531ED3902
SCBDF33SXSC021893	372531ED3902
SCBDF33SXSC021943	372531ED3902
SCBDF33SXSC022011	372531ED3902
SCBDR4ZG0SC021983	372531ED3902
SCBDR4ZG0SC022003	372531ED3902
SCBDR4ZG0SC022017	372531ED3902
SCBDR4ZG0SC022048	372531ED3902
SCBDR4ZG1SC021913	372531ED3902
SCBDR4ZG4SC021971	372531ED3902
SCBDR4ZG5SC021946	372531ED3902
SCBDR4ZG7SC021981	372531ED3902
SCBDR4ZGXSC021960	372531ED3902

SCBCF13S2SC022066	372531ED3902
SCBCF13S3SC022044	372531ED3902
SCBCF13S3SC022058	372531ED3902
SCBCF13S6SC022054	372531ED3902
SCBCF13S7SC022029	372531ED3902
SCBCG13S9SC022062	372531ED3902
SCBCR2ZG1SC021944	372531ED3902
SCBCR2ZG8SC022055	372531ED3902
SCBCR2ZGXSC022025	372531ED3902
SCBDF33S4SC021968	372531ED3902
SCBDF33S4SC021999	372531ED3902
SCBDF33S6SC021941	372531ED3902
SCBDF33S8SC022038	372531ED3902
SCBDR4ZG3SC022030	372531ED3902
SCBDR4ZG8SC021990	372531ED3902
SCBDR4ZG8SC022041	372531ED3902
SCBDR4ZG9SC021996	372531ED3902
SCBCF13S0SC022079	372531ED3902
SCBCF13S9SC022078	372531ED3902
SCBCF13SXSC022073	372531ED3902
SCBCG13S7SC022075	372531ED3902
SCBCG13S8SC022070	372531ED3902
SCBDF33S1SC022074	372531ED3902
SCBDF33S5SC022059	372531ED3902
SCBDF33S6SC022023	372531ED3902
SCBDF33S8SC021925	372531ED3902
SCBDR4ZG0SC022051	372531ED3902
SCBDR4ZG6SC022071	372531ED3902
SCBDR4ZG9SC022033	372531ED3902
SCBDR4ZG9SC022064	372531ED3902
SCBDR4ZGXSC022056	372531ED3902
SCBCF13S0SC022034	372531ED3902
SCBCF13S1SC022060	372531ED3902
SCBCF13S4SC022022	372531ED3902
SCBCF13S7SC022094	372531ED3902
SCBCF13SXSC022106	372531ED3902
SCBCG13S0SC022113	372531ED3902
SCBCG13S5SC022110	372531ED3902
SCBCG13S7SC022089	372531ED3902
SCBCG13S9SC022031	372531ED3902
SCBCJ13S1SC021988	372531ED3902
SCBCR2ZG0SC022096	372531ED3902
SCBCR2ZG1SC022088	372531ED3902
SCBCR2ZG2SC021936	372531ED3902
SCBCR2ZG5SC022112	372531ED3902

SCBCR2ZG6SC022068	372531ED3902
SCBCR2ZG8SC022069	372531ED3902
SCBDF33S2SC021774	372531ED3902
SCBDF33S7SC022080	372531ED3902
SCBDF33S8SC021908	372531ED3902
SCBDF33S8SC021956	372531ED3902
SCBDR4ZG0SC021904	372531ED3902
SCBDR4ZG2SC022021	372531ED3902
SCBDR4ZG2SC022097	372531ED3902
SCBDR4ZG6SC022104	372531ED3902
SCBCF13S2SC022102	372531ED3902
SCBCF13S9SC022100	372531ED3902
SCBCG13S3SC022140	372531ED3902
SCBCG13S4SC022082	372531ED3902
SCBCG13S8SC022098	372531ED3902
SCBCG13S8SC022134	372531ED3902
SCBCR2ZG0SC022132	372531ED3902
SCBDF33S1SC021992	372531ED3902
SCBDF33S6SC022118	372531ED3902
SCBDF33S7SC022077	372531ED3902
SCBDF33S7SC022130	372531ED3902
SCBDF33S8SC021701	372531ED3902
SCBDF33S9SC022114	372531ED3902
SCBDR4ZG5SC022045	372531ED3902
SCBDR4ZG5SC022143	372531ED3902
SCBDR4ZG6SC022135	372531ED3902
SCBDR4ZG8SC021987	372531ED3902
SCBCF13S2SC022052	372531ED3902
SCBCF13S2SC022116	372531ED3902
SCBCF13S2SC022150	372531ED3902
SCBCF13S3SC022156	372531ED3902
SCBCF13S8SC022184	372531ED3902
SCBCF13S9SC021903	372531ED3902
SCBCF13S9SC022050	372531ED3902
SCBCF1ZG8SC022155	372531ED3902
SCBCG13S0SC022175	372531ED3902
SCBCR2ZG4SC022148	372531ED3902
SCBCR2ZG7SC022161	372531ED3902
SCBCR2ZG9SC022128	372531ED3902
SCBDF33S4SC022151	372531ED3902
SCBDF33S9SC021884	372531ED3902
SCBDR4ZG1SC021863	372531ED3902
SCBDR4ZG5SC022109	372531ED3902
SCBDR4ZG7SC021544	372531ED3902
SCBDR4ZGXSC022168	372531ED3902

SCBDR4ZGXSC022171	372531ED3902
SCBCF13S1SC022124	372531ED3902
SCBCF13S2SC022181	372531ED3902
SCBCF13S3SC022187	372531ED3902
SCBCF13S4SC022120	372531ED3902
SCBCF13S5SC022157	372531ED3902
SCBCF13S5SC022174	372531ED3902
SCBCF13S6SC022085	372531ED3902
SCBCF13S8SC022153	372531ED3902
SCBCF13SXSC022137	372531ED3902
SCBCG13S8SC022179	372531ED3902
SCBCG13SXSC022166	372531ED3902
SCBCR2ZG0SC022163	372531ED3902
SCBCR2ZG5SC022207	372531ED3902
SCBDF33S2SC022195	372531ED3902
SCBDF33S3SC022173	372531ED3902
SCBDR4ZG0SC021952	372531ED3902
SCBDR4ZG1SC022138	372531ED3902
SCBDR4ZG5SC022093	372531ED3902
SCBDR4ZG5SC022191	372531ED3902
SCBDR4ZG8SC022007	372531ED3902
SCBDR4ZG9SC022159	372531ED3902
SCBCF13S3SC022027	372531ED3902
SCBCF13S5SC021980	372531ED3902
SCBCF13S9SC022193	372531ED3902
SCBDR4ZG6SC021812	372531ED3902
SCBDR4ZG8SC022122	372531ED3902
SCBDR4ZGXSC022087	372531ED3902
SCBCF13S3SC022190	372531ED3902
SCBCF13S4SC021923	372531ED3902
SCBCF13S6SC022247	372531ED3902
SCBCG13S0SC022225	372531ED3902
SCBCG13S1SC022220	372531ED3902
SCBCG13S2SC022243	372531ED3902
SCBCG13S3SC022204	372531ED3902
SCBCG13S5SC022236	372531ED3902
SCBCR2ZG1SC022222	372531ED3902
SCBCR2ZG3SC022108	372531ED3902
SCBCR2ZG3SC022254	372531ED3902
SCBCR2ZG5SC022241	372531ED3902
SCBDF33S0SC022146	372531ED3902
SCBDF33S0SC022227	372531ED3902
SCBDF33S1SC022186	372531ED3902
SCBDF33S2SC022245	372531ED3902
SCBDR4ZG4SC022182	372531ED3902

SCBDR4ZG4SC022201	372531ED3902
SCBDR4ZG9SC022209	372531ED3902
SCBDR4ZGXSC022199	372531ED3902
SCBDR4ZGXSC022218	372531ED3902
SCBCF13S1SC022169	372531ED3902
SCBCF13S2SC022259	372531ED3902
SCBCF13S3SC022271	372531ED3902
SCBCF13S4SC022263	372531ED3902
SCBCF13S7SC022256	372531ED3902
SCBCF13S9SC022212	372531ED3902
SCBCG13S0SC022239	372531ED3902
SCBCG13S0SC022273	372531ED3902
SCBCG13S1SC021729	372531ED3902
SCBCG13SXSC022233	372531ED3902
SCBCR2ZG8SC022217	372531ED3902
SCBCR2ZG8SC022234	372531ED3902
SCBDF33S2SC022164	372531ED3902
SCBDF33S2SC022214	372531ED3902
SCBDF33S5SC022269	372531ED3902
SCBDF33S6SC022250	372531ED3902
SCBDF33S8SC022279	372531ED3902
SCBDF3ZG5SC022257	372531ED3902
SCBDR4ZG3SC022237	372531ED3902
SCBDR4ZG8SC022248	372531ED3902
SCBCF13S0SC022289	372531ED3902
SCBCF13S0SC022311	372531ED3902
SCBCF13S1SC022298	372531ED3902
SCBCF13S2SC022293	372531ED3902
SCBCF13S3SC022285	372531ED3902
SCBCF13S4SC022277	372531ED3902
SCBCF13S9SC022307	372531ED3902
SCBCF1ZG2SC022314	372531ED3902
SCBCR2ZG0SC022177	372531ED3902
SCBCR2ZG4SC022117	372531ED3902
SCBCR2ZGXSC021974	372531ED3902
SCBDF33S4SC021937	372531ED3902
SCBDF33SXSC022283	372531ED3902
SCBDR4ZG0SC022101	372531ED3902
SCBDR4ZG0SC022275	372531ED3902
SCBDR4ZG8SC022265	372531ED3902
SCBCF13S2SC022035	372531ED3902
SCBCF13S3SC022304	372531ED3902
SCBCF13S4SC022246	372531ED3902
SCBCF13S6SC022006	372531ED3902
SCBCF13S6SC022300	372531ED3902

SCBCF13S8SC022301	372531ED3902
SCBCG13S0SC022337	372531ED3902
SCBCG13S2SC022324	372531ED3902
SCBCG13S6SC022231	372531ED3902
SCBCG13S7SC022142	372531ED3902
SCBCR2ZG4SC022280	372531ED3902
SCBCR2ZG6SC022216	372531ED3902
SCBDF33S7SC022287	372531ED3902
SCBDR33S2SC022320	372531ED3902
SCBDR4ZG2SC022309	372531ED3902
SCBDR4ZG4SC022294	372531ED3902
SCBDR4ZG8SC022296	372531ED3902
SCBCF13S5SC022322	372531ED3902
SCBCF13S6SC022202	372531ED3902
SCBCF13S8SC022363	372531ED3902
SCBCG13S3SC022333	372531ED3902
SCBCJ13S5SC022366	372531ED3902
SCBDF33S2SC022326	372531ED3902
SCBDF33S5SC022272	372531ED3902
SCBDF33S6SC022359	372531ED3902
SCBDF33S9SC022291	372531ED3902
SCBDF33SXSC022302	372531ED3902
SCBDR4ZGXSC022364	372531ED3902
SCBCF13S1SC022351	372531ED3902
SCBCF13S2SC022357	372531ED3902
SCBCF13S3SC022318	372531ED3902
SCBCF13S7SC022211	372531ED3902
SCBCF13S7SC022371	372531ED3902
SCBCJ13S4SC022374	372531ED3902
SCBCR13SXSC022341	372531ED3902
SCBCR2ZG3SC022335	372531ED3902
SCBCR2ZG3SC022349	372531ED3902
SCBDF33S2SC022343	372531ED3902
SCBDF33S6SC022345	372531ED3902
SCBDF33SXSC022316	372531ED3902
SCBDF3ZG9SC022083	372531ED3902
SCBDR4ZG5SC022224	372531ED3902
SCBDR4ZG5SC022305	372531ED3902
SCBDR4ZG5SC022367	372531ED3902
SCBDR4ZG6SC022328	372531ED3902
SCBDR4ZGXSC022252	372531ED3902
SCBDF33S6SC022197	372531ED3902
SCBCF13S9SC022131	372531ED3902
SCBCJ13S4SC021967	372531ED3902
SCBCR2ZG4SC022344	372531ED3902

SCBCR2ZG6SC022040	372531ED3902
SCBCF13S6SC021972	372531ED3902
SCBCJ13S1SC022042	372531ED3902
SCBCJ13S7SC021316	372531ED3903
SCBCF13S3SC022206	372531ED3903
SCBCF13S8SC022332	372531ED3903
SCBCG13S7SC022092	372531ED3903
SCBDF33S5SC022336	372531ED3903
SCBDF33SXSC022347	372531ED3903
SCBCG13S4SC022356	372531ED3903
SCBDR4ZGXSC022090	372531ED3903
SCBCR13SXSC021917	372531ED3903
SCBDF33S0SC022339	372531ED3903
SCBCF13S8SC022251	372531ED3903
SCBCG13S5SC021636	372531ED3903
SCBDF33S7SC022323	372531ED3903
SCBDR4ZG9SC022355	372531ED3903
SCBCF13S6SC022281	372531ED3903
SCBDR4ZG0SC022373	372531ED3902
SCBDR4ZG6SC021826	372531ED3902
SCBCG13S0SC021897	372531ED3902
SCBCG13S0SC021916	372531ED3902
SCBCG13S6SC021998	372531ED3902
SCBDG33S6SC022312	372531ED3902
SCBDG33S9SC021915	372531ED3902
SCBCF13S1SC022267	372531ED3902
SCBCF13S5SC022188	372531ED3903
SCBCH13S1SC022330	372531ED3903
SCBCH13S1SC022361	372531ED3902
SCBDH33S2SC022370	372531ED3903
SCBCF13S5SC022353	372531ED3903
SCBDF33S4SC022229	372531ED3902

AMERICAS	ASIA PACIFIC	CHINESE MAINLAND HK AND MACAO
SCBCJ13S1SC021313	SCBCF13S0SC022079	SCBDR33S2SC022320
SCBCJ13S7SC021316	SCBCF13S1SC021264	SCBCF13S2SC022116
SCBCR2ZG0SC021367	SCBCF13S1SC021460	SCBCF13S5SC021381
SCBCR2ZG0SC021370	SCBCF13S1SC021684	SCBCG13S0SC021527
SCBCR2ZG0SC021644	SCBCF13S1SC022124	SCBCG13S0SC021804
SCBCR2ZG0SC021661	SCBCF13S1SC022298	SCBCG13S0SC021818
SCBCR2ZG0SC021921	SCBCF13S2SC021905	SCBCG13S0SC021866
SCBCR2ZG0SC022096	SCBCF13S2SC022181	SCBCG13S0SC021883
SCBCR2ZG0SC022132	SCBCF13S3SC022156	SCBCG13S0SC021897
SCBCR2ZG0SC022163	SCBCF13S3SC022271	SCBCG13S0SC021916
SCBCR2ZG0SC022177	SCBCF13S3SC022304	SCBCG13S0SC021950
SCBCR2ZG1SC021300	SCBCF13S4SC021761	SCBCG13S0SC022113
SCBCR2ZG1SC021426	SCBCF13S5SC021770	SCBCG13S0SC022175
SCBCR2ZG1SC021572	SCBCF13S6SC021289	SCBCG13S0SC022225
SCBCR2ZG1SC021670	SCBCF13S6SC021535	SCBCG13S0SC022239
SCBCR2ZG1SC021734	SCBCF13S6SC022054	SCBCG13S0SC022273
SCBCR2ZG1SC021801	SCBCF13S6SC022281	SCBCG13S0SC022337
SCBCR2ZG1SC021927	SCBCF13S7SC022371	SCBCG13S1SC021309
SCBCR2ZG1SC021944	SCBCF13S8SC021780	SCBCG13S1SC021312
SCBCR2ZG1SC022088	SCBCF13S8SC021844	SCBCG13S1SC021696
SCBCR2ZG1SC022222	SCBCF13S8SC021875	SCBCG13S1SC021729
SCBCR2ZG2SC021256	SCBCF13S8SC021942	SCBCG13S1SC021763
SCBCR2ZG2SC021497	SCBCF13S8SC022251	SCBCG13S1SC021813
SCBCR2ZG2SC021516	SCBCF13S8SC022301	SCBCG13S1SC021830
SCBCR2ZG2SC021550	SCBCF13S8SC022332	SCBCG13S1SC021861
SCBCR2ZG2SC021631	SCBCF13S9SC021786	SCBCG13S1SC022220
SCBCR2ZG2SC021662	SCBCF13S9SC021920	SCBCG13S2SC021268
SCBCR2ZG2SC021712	SCBCF13S9SC022002	SCBCG13S2SC021285
SCBCR2ZG2SC021936	SCBCF13S9SC022193	SCBCG13S2SC021562
SCBCR2ZG2SC022004	SCBCF13SXSC021599	SCBCG13S2SC021934
SCBCR2ZG3SC021279	SCBCF13SXSC022106	SCBCG13S2SC021982
SCBCR2ZG3SC021282	SCBCJ13S1SC022042	SCBCG13S2SC022016
SCBCR2ZG3SC021377	SCBCJ13S4SC021967	SCBCG13S2SC022243
SCBCR2ZG3SC021508	SCBCJ13S8SC021292	SCBCG13S2SC022324
SCBCR2ZG3SC021556	SCBCJ13S8SC021339	SCBCG13S3SC021487
SCBCR2ZG3SC021752	SCBCR13S1SC021627	SCBCG13S3SC021909
SCBCR2ZG3SC021766	SCBCR13S2SC021278	SCBCG13S3SC021991
SCBCR2ZG3SC021900	SCBCR13S4SC021363	SCBCG13S3SC022140
SCBCR2ZG3SC022108	SCBCR13S9SC021553	SCBCG13S3SC022204
SCBCR2ZG3SC022254	SCBCR13SXSC021383	SCBCG13S3SC022333
SCBCR2ZG3SC022335	SCBCR13SXSC021917	SCBCG13S4SC021420
SCBCR2ZG3SC022349	SCBCR13SXSC022341	SCBCG13S4SC021501
SCBCR2ZG4SC021906	SCBDF33S1SC021829	SCBCG13S4SC021773
SCBCR2ZG4SC021954	SCBDF33S2SC022326	SCBCG13S4SC021837

SCBCR2ZG4SC022117	SCBDF33S3SC022173	SCBCG13S4SC022082
SCBCR2ZG4SC022148	SCBDF33S4SC021291	SCBCG13S4SC022356
SCBCR2ZG4SC022280	SCBDF33S5SC022014	SCBCG13S5SC021393
SCBCR2ZG4SC022344	SCBDF33S5SC022272	SCBCG13S5SC021488
SCBCR2ZG5SC021414	SCBDF33S6SC021941	SCBCG13S5SC021636
SCBCR2ZG5SC021445	SCBDF33S6SC022023	SCBCG13S5SC021832
SCBCR2ZG5SC021462	SCBDF33S6SC022345	SCBCG13S5SC021846
SCBCR2ZG5SC021512	SCBDF33S7SC021835	SCBCG13S5SC021958
SCBCR2ZG5SC021719	SCBDF33S8SC021567	SCBCG13S5SC022110
SCBCR2ZG5SC021798	SCBDF33S9SC021318	SCBCG13S5SC022236
SCBCR2ZG5SC021994	SCBDF33S9SC021870	SCBCG13S6SC021404
SCBCR2ZG5SC022112	SCBDF33SXSC022302	SCBCG13S6SC021578
SCBCR2ZG5SC022207	SCBDF33SXSC022347	SCBCG13S6SC021984
SCBCR2ZG5SC022241		SCBCG13S6SC021998
SCBCR2ZG6SC021440		SCBCG13S6SC022231
SCBCR2ZG6SC021485		SCBCG13S7SC021444
SCBCR2ZG6SC021583		SCBCG13S7SC021475
SCBCR2ZG6SC021700		SCBCG13S7SC021783
SCBCR2ZG6SC021809		SCBCG13S7SC021850
SCBCR2ZG6SC021874		SCBCG13S7SC021914
SCBCR2ZG6SC021986		SCBCG13S7SC021945
SCBCR2ZG6SC022037		SCBCG13S7SC021976
SCBCR2ZG6SC022040		SCBCG13S7SC022075
SCBCR2ZG6SC022068		SCBCG13S7SC022089
SCBCR2ZG6SC022216		SCBCG13S7SC022092
SCBCR2ZG7SC021494		SCBCG13S7SC022142
SCBCR2ZG7SC021558		SCBCG13S8SC021386
SCBCR2ZG7SC021642		SCBCG13S8SC021422
SCBCR2ZG7SC021673		SCBCG13S8SC021436
SCBCR2ZG7SC021821		SCBCG13S8SC021467
SCBCR2ZG7SC021852		SCBCG13S8SC021520
SCBCR2ZG7SC022015		SCBCG13S8SC021615
SCBCR2ZG7SC022161		SCBCG13S8SC021789
SCBCR2ZG8SC021360		SCBCG13S8SC021825
SCBCR2ZG8SC021410		SCBCG13S8SC021940
SCBCR2ZG8SC021665		SCBCG13S8SC022070
SCBCR2ZG8SC021827		SCBCG13S8SC022098
SCBCR2ZG8SC021858		SCBCG13S8SC022134
SCBCR2ZG8SC021889		SCBCG13S8SC022179
SCBCR2ZG8SC022055		SCBCG13S9SC021350
SCBCR2ZG8SC022069		SCBCG13S9SC021400
SCBCR2ZG8SC022217		SCBCG13S9SC021591
SCBCR2ZG8SC022234		SCBCG13S9SC022031
SCBCR2ZG9SC021433		SCBCG13S9SC022062
SCBCR2ZG9SC021500		SCBCG13SXSC021356

SCBCR2ZG9SC021707		SCBCG13SXSC021373
SCBCR2ZG9SC022047		SCBCG13SXSC021406
SCBCR2ZG9SC022128		SCBCG13SXSC021454
SCBCR2ZGXSC021344		SCBCG13SXSC021728
SCBCR2ZGXSC021876		SCBCG13SXSC021759
SCBCR2ZGXSC021912		SCBCG13SXSC021776
SCBCR2ZGXSC021957		SCBCG13SXSC021843
SCBCR2ZGXSC021974		SCBCG13SXSC021938
SCBCR2ZGXSC022025		SCBCG13SXSC021969
SCBDR4ZG0SC021384		SCBCG13SXSC022166
SCBDR4ZG0SC021448		SCBCG13SXSC022233
SCBDR4ZG0SC021482		SCBDF33S5SC022336
SCBDR4ZG0SC021532		SCBDF33S6SC021857
SCBDR4ZG0SC021577		SCBDG33S3SC021442
SCBDR4ZG0SC021658		SCBDG33S3SC021859
SCBDR4ZG0SC021675		SCBDG33S6SC021502
SCBDR4ZG0SC021689		SCBDG33S6SC022312
SCBDR4ZG0SC021711		SCBDG33S9SC021915
SCBDR4ZG0SC021854		
SCBDR4ZG0SC021904		
SCBDR4ZG0SC021952		
SCBDR4ZG0SC021983		
SCBDR4ZG0SC022003		
SCBDR4ZG0SC022017		
SCBDR4ZG0SC022048		
SCBDR4ZG0SC022051		
SCBDR4ZG0SC022101		
SCBDR4ZG0SC022275		
SCBDR4ZG0SC022373		
SCBDR4ZG1SC021314		
SCBDR4ZG1SC021345		
SCBDR4ZG1SC021362		
SCBDR4ZG1SC021412		
SCBDR4ZG1SC021524		
SCBDR4ZG1SC021538		
SCBDR4ZG1SC021569		
SCBDR4ZG1SC021720		
SCBDR4ZG1SC021863		
SCBDR4ZG1SC021877		
SCBDR4ZG1SC021913		
SCBDR4ZG1SC022138		
SCBDR4ZG2SC021287		
SCBDR4ZG2SC021371		
SCBDR4ZG2SC021547		
SCBDR4ZG2SC021693		

SCBDR4ZG2SC021743		
SCBDR4ZG2SC021757		
SCBDR4ZG2SC021760		
SCBDR4ZG2SC021788		
SCBDR4ZG2SC021841		
SCBDR4ZG2SC021872		
SCBDR4ZG2SC022021		
SCBDR4ZG2SC022097		
SCBDR4ZG2SC022309		
SCBDR4ZG3SC021461		
SCBDR4ZG3SC021542		
SCBDR4ZG3SC021573		
SCBDR4ZG3SC021668		
SCBDR4ZG3SC021685		
SCBDR4ZG3SC021797		
SCBDR4ZG3SC021864		
SCBDR4ZG3SC022030		
SCBDR4ZG3SC022237		
SCBDR4ZG4SC021260		
SCBDR4ZG4SC021310		
SCBDR4ZG4SC021338		
SCBDR4ZG4SC021355		
SCBDR4ZG4SC021419		
SCBDR4ZG4SC021601		
SCBDR4ZG4SC021730		
SCBDR4ZG4SC021839		
SCBDR4ZG4SC021971		
SCBDR4ZG4SC022182		
SCBDR4ZG4SC022201		
SCBDR4ZG4SC022294		
SCBDR4ZG5SC021266		
SCBDR4ZG5SC021283		
SCBDR4ZG5SC021302		
SCBDR4ZG5SC021560		
SCBDR4ZG5SC021705		
SCBDR4ZG5SC021753		
SCBDR4ZG5SC021784		
SCBDR4ZG5SC021848		
SCBDR4ZG5SC021901		
SCBDR4ZG5SC021946		
SCBDR4ZG5SC022045		
SCBDR4ZG5SC022093		
SCBDR4ZG5SC022109		
SCBDR4ZG5SC022143		
SCBDR4ZG5SC022191		

SCBDR4ZG5SC022224		
SCBDR4ZG5SC022305		
SCBDR4ZG5SC022367		
SCBDR4ZG6SC021258		
SCBDR4ZG6SC021468		
SCBDR4ZG6SC021471		
SCBDR4ZG6SC021552		
SCBDR4ZG6SC021633		
SCBDR4ZG6SC021647		
SCBDR4ZG6SC021812		
SCBDR4ZG6SC021826		
SCBDR4ZG6SC022071		
SCBDR4ZG6SC022104		
SCBDR4ZG6SC022135		
SCBDR4ZG6SC022328		
SCBDR4ZG7SC021270		
SCBDR4ZG7SC021334		
SCBDR4ZG7SC021348		
SCBDR4ZG7SC021379		
SCBDR4ZG7SC021446		
SCBDR4ZG7SC021463		
SCBDR4ZG7SC021530		
SCBDR4ZG7SC021544		
SCBDR4ZG7SC021771		
SCBDR4ZG7SC021964		
SCBDR4ZG7SC021981		
SCBDR4ZG8SC021326		
SCBDR4ZG8SC021388		
SCBDR4ZG8SC021424		
SCBDR4ZG8SC021651		
SCBDR4ZG8SC021679		
SCBDR4ZG8SC021682		
SCBDR4ZG8SC021987		
SCBDR4ZG8SC021990		
SCBDR4ZG8SC022007		
SCBDR4ZG8SC022041		
SCBDR4ZG8SC022122		
SCBDR4ZG8SC022248		
SCBDR4ZG8SC022265		
SCBDR4ZG8SC022296		
SCBDR4ZG9SC021254		
SCBDR4ZG9SC021402		
SCBDR4ZG9SC021450		
SCBDR4ZG9SC021593		
SCBDR4ZG9SC021626		

SCBDR4ZG9SC021643		
SCBDR4ZG9SC021724		
SCBDR4ZG9SC021805		
SCBDR4ZG9SC021996		
SCBDR4ZG9SC022033		
SCBDR4ZG9SC022064		
SCBDR4ZG9SC022159		
SCBDR4ZG9SC022209		
SCBDR4ZG9SC022355		
SCBDR4ZGXSC021294		
SCBDR4ZGXSC021330		
SCBDR4ZGXSC021375		
SCBDR4ZGXSC021408		
SCBDR4ZGXSC021747		
SCBDR4ZGXSC021831		
SCBDR4ZGXSC021960		
SCBDR4ZGXSC022056		
SCBDR4ZGXSC022087		
SCBDR4ZGXSC022090		
SCBDR4ZGXSC022168		
SCBDR4ZGXSC022171		
SCBDR4ZGXSC022199		
SCBDR4ZGXSC022218		
SCBDR4ZGXSC022252		
SCBDR4ZGXSC022364		

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

EUROPE	INTERNAL	MIDDLE EAST AFRICA & INDIA
SCBDG33SXSC021518	SCBDJ33S7SC021767	SCBDG33S7SC021394
SCBCF13S0SC021546	SCBCF13S0SC021255	SCBCF13S3SC021332
SCBCF13S0SC021692	SCBCF13S1SC021717	SCBCF1ZG1SC021963
SCBCF13S0SC021806	SCBCF13S2SC021709	SCBCF1ZG2SC022314
SCBCF13S0SC021840	SCBCF13S2SC022052	SCBCF1ZG5SC021688
SCBCF13S0SC021868	SCBCF13S3SC021296	SCBCF1ZG7SC021756
SCBCF13S0SC022034	SCBCF13S5SC022174	SCBCF1ZG8SC021457
SCBCF13S0SC022289	SCBCF13S7SC022094	SCBCF1ZG8SC021796
SCBCF13S0SC022311	SCBCF13S7SC022211	SCBCF1ZG8SC021894
SCBCF13S1SC021328	SCBCF13SXSC021814	SCBCF1ZG8SC022009
SCBCF13S1SC021653	SCBCG13S6SC021595	SCBCF1ZG8SC022155
SCBCF13S1SC021748	SCBCG13S8SC021324	SCBCF1ZG9SC021418
SCBCF13S1SC021961	SCBDF33S0SC021322	SCBCF1ZGXSC021458
SCBCF13S1SC022060	SCBDF33S0SC021465	SCBCH13S1SC022330
SCBCF13S1SC022267	SCBDF33S0SC021935	SCBCH13S1SC022361
SCBCF13S2SC021810	SCBDF33S1SC021975	SCBCH13S6SC021609
SCBCF13S2SC021970	SCBDF33S2SC021774	SCBCJ13S1SC021649
SCBCF13S2SC022066	SCBDF33S2SC022245	SCBCJ13S2SC021336
SCBCF13S2SC022102	SCBDF33S4SC021663	SCBCJ13S3SC021331
SCBCF13S2SC022259	SCBDF33S7SC021298	SCBCJ13S4SC021452
SCBCF13S2SC022293	SCBDF33S8SC021276	SCBCJ13S8SC021390
SCBCF13S2SC022357	SCBDF33S8SC021438	SCBCJ1ZG7SC021531
SCBCF13S3SC021430	SCBDF33S8SC021505	SCBCJ1ZG9SC021353
SCBCF13S3SC021623	SCBDF33S8SC021794	SCBDF33S3SC021816
SCBCF13S3SC021931	SCBDF33S8SC022038	SCBDF3ZG1SC021476
SCBCF13S3SC022027	SCBDF33SXSC021778	SCBDF3ZG5SC021867
SCBCF13S3SC022044	SCBDG33S4SC021496	SCBDF3ZG5SC022257
SCBCF13S3SC022058		SCBDF3ZG9SC022083
SCBCF13S3SC022187		
SCBCF13S3SC022190		
SCBCF13S3SC022206		
SCBCF13S3SC022285		
SCBCF13S3SC022318		
SCBCF13S4SC021274		
SCBCF13S4SC021470		
SCBCF13S4SC021582		
SCBCF13S4SC021646		
SCBCF13S4SC021680		
SCBCF13S4SC021713		
SCBCF13S4SC021856		
SCBCF13S4SC021887		
SCBCF13S4SC021890		
SCBCF13S4SC022019		
SCBCF13S4SC022120		

SCBCF13S4SC022263		
SCBCF13S4SC022277		
SCBCF13S5SC021347		
SCBCF13S5SC021431		
SCBCF13S5SC021509		
SCBCF13S5SC021607		
SCBCF13S5SC021610		
SCBCF13S5SC021624		
SCBCF13S5SC021638		
SCBCF13S5SC021817		
SCBCF13S5SC021879		
SCBCF13S5SC022000		
SCBCF13S5SC022157		
SCBCF13S5SC022188		
SCBCF13S6SC021504		
SCBCF13S6SC021891		
SCBCF13S6SC021910		
SCBCF13S6SC022006		
SCBCF13S6SC022202		
SCBCF13S6SC022247		
SCBCF13S7SC021320		
SCBCF13S7SC021396		
SCBCF13S7SC021477		
SCBCF13S7SC021480		
SCBCF13S7SC021589		
SCBCF13S7SC021723		
SCBCF13S7SC021737		
SCBCF13S7SC021740		
SCBCF13S7SC021849		
SCBCF13S7SC021978		
SCBCF13S7SC022029		
SCBCF13S8SC021259		
SCBCF13S8SC021536		
SCBCF13S8SC021570		
SCBCF13S8SC021617		
SCBCF13S8SC021634		
SCBCF13S8SC022153		
SCBCF13S8SC022184		
SCBCF13S9SC021660		
SCBCF13S9SC021691		
SCBCF13S9SC021769		
SCBCF13S9SC021822		
SCBCF13S9SC021903		
SCBCF13S9SC021965		
SCBCF13S9SC022078		

SCBCF13S9SC022131		
SCBCF13S9SC022212		
SCBCF13S9SC022307		
SCBCF13SXSC021490		
SCBCF13SXSC021733		
SCBCF13SXSC022073		
SCBCJ13S0SC021304		
SCBCJ13S1SC021988		
SCBCJ13S2SC021790		
SCBCJ13S4SC021340		
SCBCJ13S4SC022374		
SCBCJ13S5SC022366		
SCBCJ13S8SC021308		
SCBDF33S0SC021398		
SCBDF33S0SC021434		
SCBDF33S0SC021580		
SCBDF33S0SC021739		
SCBDF33S0SC022146		
SCBDF33S0SC022339		
SCBDF33S1SC021510		
SCBDF33S1SC021930		
SCBDF33S1SC021992		
SCBDF33S1SC022074		
SCBDF33S1SC022186		
SCBDF33S2SC021306		
SCBDF33S2SC021368		
SCBDF33S2SC021564		
SCBDF33S2SC021919		
SCBDF33S2SC022164		
SCBDF33S2SC022195		
SCBDF33S2SC022214		
SCBDF33S2SC022343		
SCBDF33S3SC021489		
SCBDF33S3SC021654		
SCBDF33S3SC021699		
SCBDF33S3SC021802		
SCBDF33S4SC021629		
SCBDF33S4SC021727		
SCBDF33S4SC021968		
SCBDF33S4SC021999		
SCBDF33S4SC022229		
SCBDF33S5SC021252		
SCBDF33S5SC021428		
SCBDF33S5SC021493		
SCBDF33S5SC021672		

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

UNITED KINGDOM
SCBDH33S2SC022370
SCBCF13S0SC021742
SCBCF13S0SC021885
SCBCF13S1SC021605
SCBCF13S1SC022012
SCBCF13S1SC022169
SCBCF13S1SC022351
SCBCF13S2SC021614
SCBCF13S2SC022035
SCBCF13S2SC022150
SCBCF13S3SC021539
SCBCF13S3SC021587
SCBCF13S3SC021704
SCBCF13S3SC021928
SCBCF13S4SC021551
SCBCF13S4SC021565
SCBCF13S4SC021677
SCBCF13S4SC021744
SCBCF13S4SC021775
SCBCF13S4SC021923
SCBCF13S4SC022022
SCBCF13S4SC022246
SCBCF13S5SC021834
SCBCF13S5SC021980
SCBCF13S5SC022322
SCBCF13S5SC022353
SCBCF13S6SC021972
SCBCF13S6SC022085
SCBCF13S6SC022300
SCBCF13S7SC021267
SCBCF13S7SC021575
SCBCF13S7SC021656
SCBCF13S7SC021754
SCBCF13S7SC021785
SCBCF13S7SC022256
SCBCF13S8SC020919
SCBCF13S8SC021262
SCBCF13S8SC022363
SCBCF13S9SC022050
SCBCF13S9SC022100
SCBCF13SXSC021473
SCBCF13SXSC022137
SCBDF33S0SC021272
SCBDF33S0SC021823

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]