

Technical Service Bulletin

Topic	93 Q6 e-tron - displayed remaining range too low
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2077771/1
Level	EH
Status	Released for publishing
Release date	May 5, 2025

New customer code

Object of complaint	Complaint type	Position
entire vehicle -> driving performance, consumption -> range	dimensional accuracy -> too low	

Vehicle data

Q6 e-tron

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
GF*	2025	A		*	*	*

Documents

Document name
master.xml
anleitung_q6_modul_anlernen_en-1.pdf
anleitung_q6_modul_anlernen_en.docx

Technical Service Bulletin

93 Q6 e-tron - displayed remaining range too low

Transaction No.: **2077771/1**

Release date: May 5, 2025

Condition

Customer states:

- Instrument cluster remaining range display implausible. When the high-voltage battery has a state of charge of 80%, a remaining range of only 124 miles is shown.
- The remaining range displayed is less than half of the expected remaining range.

Workshop findings:

- The customer complaint can be reproduced.
- The remaining range displayed is too low.
- There is a sudden drop in the remaining range displayed.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Adapt all high-voltage battery modules according to the attachment “Anleitung_Q6_Modul_anlernen.pdf”.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9325		
Damage Code:	0039		
	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2077771/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2077771**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.