

Reference	SSM76320
Models	I-PACE / X590
Title	IMC equipped vehicle no longer displays grid lines in reverse camera image after IPMB module update.
Category	Electrical
Last modified	05-May-2025 00:00:00
Symptom	206000 Warning Indicators

ContentIssue:

- Grid lines are no longer showing in the reverse camera image after a software update to IPMB camera module.

Cause:

- A change to the car configuration data was introduced during programming, resulting in the grid lines no longer being displayed.

Action:

1. Do not replace the IPMB camera module.
2. Raise a Technical Assistance case and reference this SSM 76320
3. Guidance and information to correct the concern will be provided through the technical assistance case.

anBhdHRicnM7MjAyNS0wNS0yMFQzMjpyOToxMk42NFaOzEzNi4yMjYuODEuODU7