



STAR ONLINE PUBLICATION



Case Number: S2523000056

Release Date: June 2025

Symptom/Vehicle Issue: Gap Visible Between Instrument Panel Top Cover And A Pillar Trim.

Discussion: If the customer has a visual complaint on the A-pillar trim having a noticeable gap, an update to the A-pillar trim is now available (Fig 1). Parts AD and newer will have the revised shape to resolve visual gap.




Fig 1.
AD Level Part On Right Side.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.