

GPOP - Issue Review System

Part Number: 68736094A\$, 68736095A\$, 68736466A\$

Part Description: Radio Frequency Hub Module

Issue Description: 25MY WL/WS built starting week of 6/9/25 may show up at dealerships with a message in cluster saying "key fob left vehicle" and while in RUN the vehicle may exhibit horn chips as if the fobs did leave even though they are still in the cabin. This is a known issue that is under investigation but will go away after the vehicle is brought out of shipping mode and into logistics.