

MAS004330 MCL 25-31

Circular LetterFROM: Maserati TSO
TO: Maserati Network

PERSONAL SERVICE LAB

MASTERS OF CARE

Stop Field Action

DATE: June 10, 2025

The Rapid Updates (Campaigns) in the list below will be closed starting from **June 16, 2025**. Claims received after this date will no longer be accepted.

Effective from the publication date of this document, the **Mandatory Flag** will be removed for all campaigns listed, allowing for easier management as we approach the closure period.

Campaign Number	Campaign Description	Closure Date
243	FRONT DIFFERENTIAL UPGRADE	06/16/2025
275	COOLANT LEAKAGE FROM WATER RADIATOR	06/16/2025
288	ECM SOFTWARE UPDATE	06/16/2025
294	ENGINE OIL PRESSURE SENSOR REPLACEM.	06/16/2025
306	RIDE CONFORT-FRONT SUSP. SPRINGS REP	06/16/2025
326	SIRIUS CODE ACTIVATION	06/16/2025
332	VEHICLE HEIGHT CHECK ADJUSTMENT	06/16/2025
333	ENGINE OIL SPECIFICATIONS UPDATE	06/16/2025
337	UNDERWINDSCR. AREA SEALING	06/16/2025
348	HVACR SW UPDATE	06/16/2025
353	WATER VENT PIPE REPLACEMENT	06/16/2025
355	IPC SW UPDATE	06/16/2025
364	ECM SOFTWARE UPDATE	06/16/2025

366	ECM SOFTWARE UPDATE	06/16/2025
371	ETM FACTORY RESET	06/16/2025
374	ECM SW UPDATE	06/16/2025
379	GPF - ECM SW UPDATE	06/16/2025
385	ECM SOFTWARE UPDATE	06/16/2025
388	LAMBDA SENSOR CLIP INSTALLATION	06/16/2025
390	ISTALLAZIONE IVH NELL'ETM	06/16/2025
395	CAMPAIGN 395 ECM SW UPDATE	06/16/2025
400	MHEV - FLUID LABEL REPLACEMENT	06/16/2025
406	ECM SW UPDATE	06/16/2025
427	HVAC LABEL REPLACEMENT	06/16/2025
433	IPC SW UPDATE - ECE16 SBR	06/16/2025
438	PIPE CYLINDER HEAD - COOLANT LEAKAGE	06/16/2025
440	OXIDATION ON A GROUND POINT	06/16/2025
447	M161 BADGE TRIBUTO NOT INSTALLED	06/16/2025
448	DCTM SW UPDATE	06/16/2025
449	HEADREST REPLACEMENT M157 TROFEO	06/16/2025
451	ECM SOFTWARE UPDATE V8 MY21	06/16/2025
452	GROUND POINT ON REAR CHASSIS CHECK	06/16/2025
460	CLEANING THE MAIN CAM SPARK PLUG	06/16/2025
461	FUSE F01 HOUSING CHECK	06/16/2025
462	ENGINE OIL BLOW-BY HOSE CHECK	06/16/2025
468	INCORRECT ADAPTATION DATA	06/16/2025
471	VC WRITING	06/16/2025
477	ENGINE OIL LABEL CHECK	06/16/2025
481	BRAKE CALIPER RIGID PIPES REPLACEMEN	06/16/2025
484	MC20 FUEL TANK FILLER PORT	06/16/2025
520	MC20 ENGINE MOUNT ADHESION FAILURE	06/16/2025
522	MC20 DCTM SOFTWARE UPDATE	06/16/2025
523	M157 MY22 SMOKING KIT KOREA	06/16/2025

540	WRONG LANGUAGE ONBOARD DOCUMENTATION	06/16/2025
544	M182 WRONG AMOUNT OF REFRIGERANT GAS	06/16/2025
546	GRECALE - ICS FUNCTIONALITY CHECK	06/16/2025
554	REAR TWEETER REPOSITIONING	06/16/2025
556	GRECALE - BRAKE CALIPERS CHECK	06/16/2025
565	M161 PERMANENTLY OPEN AGS GRID SET	06/16/2025
566	ETM Black Curtain	06/16/2025
587	M182 NAV MAPS NOT AVAILABLE ON IPC	06/16/2025
588	M182 RHD WIPER BLADE INTERFERENCE	06/16/2025
593	GRANTURISMO REAR WIRING CHECK	06/16/2025
595	M157 M161 BSG DRIVING BELT CHECK	06/16/2025
600	M189 RFHM PROXIMITY PARAMETER CHANGE	06/16/2025
603	M189 REAR EXHAUST SYS FIXINGS CHECK	06/16/2025
607	GRANTURISMO SPARK PLUG CLEANING	06/16/2025
610	GT STEERING WHEEL CONTROL STUCK	06/16/2025
611	MC20 WHEEL CONTROL STUCK OPT SBE	06/16/2025
615	MC20 RHT WINDSHIELD GASKET REPLACE	06/16/2025
642	M189 LIGHT BAR BEZEL REPLACEMENT	06/16/2025
10272	ECM SOFTWARE UPDATE	06/16/2025
10364	ECM SOFTWARE UPDATE	06/16/2025
10443	MC20 - DRIVER & PASSENGER SEATS	06/16/2025