

MAS004770 MCL 25-32

Circular Letter

FROM: Maserati TSO

TO: Maserati Network



Maserati

PERSONAL SERVICE LAB

MASTERS OF CARE

Levante / Grecale Rear Window Wiper Water Pipe Repair Kit

This bulletin provides important information regarding the rear window wiper washer pipe on Maserati Levante and Grecale models. If a fluid leak is detected at the connection point of the delivery pipe, it is now possible to replace only the affected pipe using a dedicated repair kit, instead of replacing the entire engine compartment wiring harness.

DATE: June 25, 2025


MODELS AFFECTED: M182 Grecale, M182 Levante (ALL MODEL YEARS)

Concern:

Washer fluid leakage may occur due to a faulty delivery pipe connection.

In previous cases, because the pipe is routed inside the corrugated engine compartment harness, replacing the entire harness was required.


To simplify repairs, a dedicated pipe repair kit is now available.



Component Details

To avoid replacing the engine compartment wiring harness, the following P/N is available:

- #675002344 = REAR WINDOW WASHER PIPE REPAIR KIT (Spare Parts Catalog -> Section #08.00-1 -> Component #22).



Please always refer to the Technical Documentation for the latest updates or contact the Maserati Helpdesk.

Workshop procedure

To claim the repair activity, you can use the following time code:

- #08.00. 999.A. (0.15 h)

Special Tools

No special tools are required for this procedure.

Thank you for your kind attention

TECHNICAL SERVICE OPERATIONS