



2025-06-13



M1674: REDESIGNED FUEL PUMP FOR SPORTSTER S AND PAN AMERICA

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2025-06-13	-	Initial release

Purpose for Service Bulletin

To inform dealers that a **new** redesigned Fuel Pump Module is available for the Sportster S and Pan America vehicles.

- The **new** Fuel Pump Module (Part No. 61200062A) has a larger fuel filter with new media and a slightly different housing to allow for assembly.
- This **new** Fuel Pump Module is **retrofittable** to all older vehicles.
- The **new** Fuel Filter (Part No. 61200123) is available separately for service but will **only fit the new Fuel Pump Module**.
- **DO NOT** mix old and new parts.
- When making warranty repairs, use the **new** Fuel Pump module (Part No. 61200062A). **Return all old inventory of** (Part No. 61200062) per Table 4.

Required Dealer Action

Table 2. Required Dealer Action

Category	Description	Required
1	Must Perform Repair	☐
2	Repair If Presenting Symptom	☒
3	Feature Pack-Customer/Dealer Paid	☐
4	Informational Purposes Only	☐

Vehicles Affected

2021-2025: Pan America (RA1250), Pan America S (RA1250S),
Pan America ST (RA1250ST), CVO Pan America (RA1250SE),
Sportster S (RH1250S)

Markets Affected

All markets affected.

Part Numbers

Refer to Table 3.

Table 3. Part Numbers

Old Part No.	Item Description	New Part No.
61200062	Fuel Pump, Module	61200062A

Dealer Inventory Instructions

- Start using the **new** fuel pump (Part No. 61200062A).

NOTE

See Figure 1. Small fuel filter (1) is shown untucked from under plastic cover.





Figure 1. Old Fuel Pump (61200062)

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

[illegible]



1. Large fuel filter

Figure 2. New Fuel Pump (61200062A)

Credit Procedure

NOTE

Enter bulletin number M1674 into Events Comments section of claim.

Do not use a Vehicle Identification Number (VIN) when submitting these claims.

Submit a warranty claim per Table 4 for all kits in dealer stock.

Table 4. Disposed Old Fuel Pump(s)

ITEM	DATA
Claim Type	DFS/PAM - Stock
Problem Part Number	61200062
Quantity	Could vary
Customer Concern Code	9203
Condition Code	2105

Return Parts

Hold all claimed parts for 60 days from date of credit issued for possible field inspection and/or request to return to factory. After 60 days, destroy and discard the parts.