

RFA DTC U3000-95 Walk Away / Approach

Concern:

- Walk Away Lock / Approach unlock function not working, RFA DTC U3000-95 may be set.

Technical Description:

- F-pace, Discovery and Discovery sport vehicles 25MY and up have "Pull type" non-deployable door handles.
- The current RFA software version ending in **-AX** does not support this door handle hardware type.
- RFA DTC U3000-95 DTC is set to indicate the handle type is not supported. The DTC should be ignored as it will not adversely affect vehicle operation.

Action:

Reference **SSM76332** (Jaguar) and **SSM76333** (LR) and follow instructions outlined.

1. Do not replace the RFA module.
2. Confirm if RFA software is at **-AX** level and if so, turn off the Walk Away Lock and Approach Unlock functions in touch screen if enabled.
3. Advise customer of upcoming RFA **-AY** software and schedule for return visit to update once available to restore Walk Away Lock and Approach Unlock function.

SSM's will be updated once the new RFA **-AY** software level is available in service and will be communicated in future TUCC call accordingly.

Discovery

- 25-26MY Discovery
- 25-26MY Discovery Sport

Jaguar

- 25-26MY F-PACE