

ENGINE COOLANT LEVEL LOW WITH NO VISIBLE LOSS OF COOLANT

Customer Voice:

- 'Coolant Level Low' message displayed on the instrument panel cluster.

Technical Description:


- The coolant level is low or close to minimum, or that the coolant level requires frequently topping up due to permeation of water content from the engine coolant through plastic pipes.

Status:

- Inspect the coolant expansion tank.
 - If coolant expansion tank 'B' is installed do not continue with this bulletin. Repair as necessary with reference to TOPIx.
 - If coolant expansion tank 'A' is installed continue to the next step.
- Inspect the coolant level in the coolant expansion tank. If the coolant is at the maximum level in the coolant expansion tank and the 'Coolant Level Low' message is displayed on the instrument panel cluster do not continue with this bulletin. Repair as necessary with reference to TOPIx.
- Continue with the instructions on the technical bulletin where you may be instructed to install a new fuel supply line and coolant expansion tank.

Range Rover

- 23-24MY Range Rover
- 23-24MY RR Sport



E363515

JLRTB02127NAS5