

AIR CONDITIONING INOPERATIVE AND DTC B1B71-11 STORED

Customer Voice:

- The air conditioner does not blow cold air.

Technical Description:

- This may be caused by an evaporator temperature sensor not operating as expected and DTC B1B71-11 'Evaporator Temperature Sensor – Circuit Short to Ground' stored.

Status:

- Engineering are currently investigating this concern.
- **SSM 76328** has been published to provide diagnostic checks for the evaporator temperature sensor circuit.
- If after following the diagnostic steps, the evaporator temperature sensor is found to be at fault, please submit an EPQR with the requested information included in the SSM to support parts return for investigation.

Defender

- 20 - 25MY Defender

Discovery

- 20 - 25MY Discovery

