

FLOOR CONSOLE COOL BOX INOPERATIVE

Customer Voice:

- The cool box is inoperative, or the cool box switch does not illuminate.

Technical Description:

- DTC B160D-87 'Cooled Centre Fridge Storage – Missing Message' may be stored.

Status:

- A new TOPIx Cloud test plan has been created for the concern.
- **SSM 76316** has been published to announce the new test plan and provide test plan root guidance.

Range Rover

- 23–25MY Range Rover (L460)
- 24-25MY RR Sport (L461)

