

Field Action Number	N25-250378 (V652.20)
Release notes	• Improvements to vehicle diagnostics. • Fixes to preserve battery life and improve charging. • Fixes to address issues with shifting. • Fixes for vehicle airflow in icy conditions. • Improvements to HVAC compressor performance. During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.
Model Year	2024 2025
Make	Chevrolet
Model	Equinox EV
Components	VICM (Vehicle Integration Control Module)