

Bulletin #: C32-0725-0640		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: July 25, 2025		Supersedes:	



# BMW PARTS BULLETIN

## TEC776 RIGHT BALL JOINT RETURN

### TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

32 10 5 A2B D08

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing wrong part in package.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC776 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC776 is valid from July 25, 2025, through August 08, 2025. The deadline for filing a claim under TEC776 is August 08, 2025. All parts must be returned to your facing RDC no later than August 22, 2025.

Please reorder the same part number if needed.

