

Bulletin #: C32-0725-0642		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: July 28, 2025		Supersedes:	



BMW PARTS BULLETIN

TEC778 BOWDEN CABLE OUTER RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

52 30 5 A1E 229

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing wrong part (pn 5A1E228) in package.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC778 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC778 is valid from July 28, 2025, through August 11, 2025. The deadline for filing a claim under TEC778 is August 11, 2025. All parts must be returned to your facing RDC no later than August 25, 2025.

Please reorder the same part number if needed.

