

Uncontrolled Copy

ID # CBR-2482

Version 1

Title

PTO Malfunction Pop Up - VN (4) - PR (4)

Abstract

Purpose of this CBR is to address Pop up message for PTO Malfunction when there is not PTO Installed.

Content

Published 8 July 2025

Valid For

Volvo Chassis - VN (4)

Mack Chassis - PR (4)

Model Year - 2025 to current

Purpose of this CBR is to address Pop up message for PTO Malfunction when there is no PTO Installed.



When encountering a unit with a pop-up message for PTO malfunction and fault code P100A15, follow steps below:

1. Check to see if unit has a PTO switch installed in dash. If there is a switch, check to see if there is a PTO solenoid installed on transmission.
2. If there is no solenoid installed on transmission please order parts below and install solenoid.

Part Number	QTY.	Description
2517341	2	Flange Screw M6x14
24036589	1	Connector, 1/4" Tube- Straight
23616853	1	Plug, Push in Plug - 1/4" Inch
23616844	2	Nipple, 1/4" - Small
24145125	1	Solenoid Valve 3/2 NC, 24V
945460	685 mm	Tube 6, 4 x 1
995627	1	Plug, Small
980464	1	Cable Tie

NOTE: If solenoid bracket is not installed please order: 24262391

3. Once solenoid is installed, please clear faults and release unit to service.

Tags

volvo

mack

vn 4

vn4

pr4

pr 4

pto

pop up

check engine light

cel

mil

Categories ★

Make and Model > Volvo > All-New VNL - VN (4)

Make and Model > Mack Americas > PR (4) - Pioneer