

VEHICLE QUARANTINE - H533/D032 - PASSENGER FRONTAL AIRBAG REPLACEMENT

VEHICLE QUARANTINE - H533/D032 - PASSENGER FRONTAL AIRBAG REPLACEMENT	
AFFECTED MODELS	21-24MY E-PACE 21-25MY Range Rover Evoque
VOLUME AFFECTED	H533 – 22 US 2 CAN D032 – 66 US 22 CAN
REPAIR	A concern has been identified on certain vehicles were, during a passenger airbag deployment, the airbag may tear as a result of improper folding of the airbag during the airbag assembly process. A replacement passenger frontal airbag will be required.
REPAIR TIME	TBA
CAMPAIGN LAUNCH	Vehicle quarantine notices were published on July 10th, 2025.
NOTES	Retailers are required to quarantine all affected vehicles that are within their control and cease releasing the vehicles for vehicle sale until repair is available and completed. A future service bulletin will be released to communicate the repair procedure. All applicable VIN applicability are immediately flagged in the warranty portal and will be shown in BBBS effective July 11 th , 2025.