

## RADIATOR UPPER COOLANT HOSE- ADRIFT – P6

### Range Rover

- 22-25MY Range Rover
- 23-25MY RR Sport

### Customer Voice:

- Vehicle is experiencing an engine coolant leak. Low coolant light is on.

### Technical Description:

- During inspection of the radiator upper coolant hose, damage is evident as a result of contact with the electric cooling fan with either 1 or both of the cable tie clips incorrectly installed, broken or missing.

### Status:

- Before removing the radiator upper coolant hose, take clear photographs showing the installed position of the hose, the location of the 2 cable tie clips (a photograph must still be taken even if 1 or both of the clips are missing), the part number of the hose and the damage caused by the contact with the electric cooling fan.
- Before installing a new radiator upper coolant hose, make sure the new hose is equipped with 2 clips.
- Only install a new radiator upper coolant hose after the photographs have been taken.
- NOTE: Ingenium I6 3.0L Petrol radiator upper coolant hose part number - LR151598
- Please raise an Electronic Product Quality Report (EPQR) which should include the information below:
  - Reference to PTS\_500
  - Reference to this SSM (SSM76338)
  - The requested photographs

SSM 76338

