

Customer Notification

Corporate Compliance
Po Box 30
MIDDLEBURY, INDIANA 46540-9218



FOREST RIVER ID: 51-1946
FCA RECALL: 25V330 / 40C

<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- o *Integrity*
- o *Safety*
- o *Quality*
- o *Customer Service*

July 2025

This Notice applies to your vehicle VIN listed above.

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

–Forest River motorized and towable products are contained in this section–

Dear Forest River Customer:

Forest River is alerting you to a FCA recall 25V330/ 40C, involving certain 2023 Cross Trail Class C, 2025 Forester Class C, 2023-2026 Nova Class B, 2025-2026 Pixel Class B Motorhomes, and 2022-2026 Rockport Work Trucks. Please see the information below which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

The Security Gateway Module (SGW) on your vehicle may prevent some communication between vehicle modules, which may result in the rearview image not displaying in a backing event. The vehicle operator may notice that the rearview image is not displayed if attempting to reference the image while backing. A rearview camera image that does not display reduces the driver's visibility of what is behind the vehicle and if not heeded, increases the risk of a crash.

OWNERS AND DEALERS: WHAT SHOULD YOU DO?

Please review and follow the notice that accompanies this letter.

Sincerely,

Forest River Inc.
Office of Corporate Compliance

This notice applies to your vehicle,

[Model Year and Model]

VIN XXXXXXXXXXXXXXXXXXXX

40C/NHTSA 25V-330

LOGO

VEHICLE PICTURE

YOUR SCHEDULING OPTIONS

1. RECOMMENDED OPTION

Call your authorized BusinessLink dealer.

2. Call the FCA Recall Assistance Center at 1-800-853-1403.

An agent can confirm part availability and help schedule an appointment.

3. Visit recalls.mopar.com, scan the QR code below, or download the Mopar Owner's Companion App.

QR Code

Get access to recall notifications, locate your nearest dealer, and more through this website or Mopar Owner's Companion App. You will be asked to provide your Vehicle Identification Number (VIN) to protect and verify your identity. The last eight characters of your VIN are provided above.

DEALERSHIP INSTRUCTIONS

Please reference Safety Recall 40C.

IMPORTANT SAFETY RECALL

Rearview Camera

Dear [Name],

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

FCA US LLC has decided that certain [2022-2025 model year (VF) Ram ProMaster] vehicles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 111 - Rear visibility.

It is extremely important to take steps now to repair your vehicle to ensure the safety of you and your passengers.

WHY DOES MY VEHICLE NEED REPAIRS?

The Security Gateway Module (SGW) on your vehicle ^[1] may prevent some communication between vehicle modules, which may result in the rearview image not displaying in a backing event. The vehicle operator may notice that the rearview image is not displayed if attempting to reference the image while backing. **A rearview camera image that does not display reduces the driver's visibility of what is behind the vehicle and if not heeded, increases the risk of a crash.**

The condition above fails to conform to the requirements of FMVSS No. 571.111 S6.2.6 requires that "The rear visibility system default to the rearview image being visible and meet the requirements of FMVSS No. 571.111 S6.2.1 (field of view) and S6.2.2 (image size) at the beginning of each backing event, regardless of any modifications to the field of view that the driver had previously selected..." and apply to other markets via direct reference to FMVSS or are implied via free trade agreements. Suspect vehicles may not display the rearview image during a backing event.

HOW DO I RESOLVE THIS IMPORTANT SAFETY ISSUE?

FCA US will repair your vehicle ^[2] free of charge (parts and labor). To do this, your dealer will reprogram the SGW with corrected software. The estimated repair time is 20 minutes. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. Ask your dealer for alternate transportation options while your vehicle is in service. Please bring this letter with you to your dealership.

**TO SCHEDULE YOUR FREE REPAIR,
CALL YOUR BUSINESSLINK DEALER TODAY**

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?

If you have already experienced this specific condition and have paid to have it repaired, you may visit www.fcarecallreimbursement.com to submit your reimbursement request online. ^[3] Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the recall repair performed.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations
FCA US LLC



Mr. Mrs. Customer
1234 Main Street
Hometown, MI 48371

[1] If you no longer own this vehicle, please help us update our records. Call the FCA Recall Assistance Center at 1-800-853-1403 to update your information.

[2] If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, or you can call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to safercar.gov.

[3] You can also mail in your original receipts and proof of payment to the following address for reimbursement consideration: FCA Customer Assistance, P.O. Box 21-8004, Auburn Hills, MI 48321-8007, Attention: Recall Reimbursement.

Note to lessors receiving this recall notice: Federal regulation requires that you forward this recall notice to the lessee within 10 days.

Customer Notification

Corporate Compliance
Po Box 30
MIDDLEBURY, INDIANA 46540-9218



FOREST RIVER ID: 51-1946
FCA RECALL: 25V330 / 40C

<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- o *Integrity*
- o *Safety*
- o *Quality*
- o *Customer Service*

August 2025

This Notice applies to your vehicle VIN listed above.

Dear Forest River Customer:

Forest River is alerting you to a FCA recall 25V330/ 40C, involving certain 2023 Cross Trail Class C, 2025 Forester Class C, 2023-2026 Nova Class B, 2025-2026 Pixel Class B Motorhomes, and 2022-2026 Rockport Work Trucks. Please see the information below which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

The Security Gateway Module (SGW) on your vehicle may prevent some communication between vehicle modules, which may result in the rearview image not displaying in a backing event. The vehicle operator may notice that the rearview image is not displayed if attempting to reference the image while backing. A rearview camera image that does not display reduces the driver's visibility of what is behind the vehicle and if not heeded, increases the risk of a crash.

OWNERS AND DEALERS: WHAT SHOULD YOU DO?

Please review and follow the notice that accompanies this letter.

Sincerely,

Forest River Inc.
Office of Corporate Compliance