



Service Bulletin

Bulletin No.: PIT6235B

Date: August, 2025

PRELIMINARY INFORMATION

Subject: MIL Illuminated-Variou Warning Messages

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024 - 2025		All	All	All	All

Involved Region or Country	North America
Condition	Service high voltage message, shift to park message or others. May not shift out of park. One pedal drive temporarily or permanently disabled. Codes B2BBC B2BBD P0607 P0CC8 P1916 P1939 P1E00 U016D U019B U11FD U053B U0073 U0131 U0140 U0151 U164E U0411 U0412 U0418 U1522 U1610 U1659 U1961 may be set or other codes may be set. Any of these symptoms or codes or others may be displayed depending on which circuits are affected.
Cause	Harness chafed at edge of cowl causing damage to circuits.

Correction

Inspect the harness in the area shown below for damage.

If the harness has a foil wrap on it inspect the harness beyond the wrap where it may have chafed on the cowl.

If damage is found, repair the circuits per SI.

Wrap the harness in tape or conduit and route it away from the cowl.



6730517



6730516



6730514



6730511



6730513



6730515

Additional SI Keywords

24, 2024, B2BBC, B2BBD, Blazer EV, chafe, circuit, cowl, firewall, high, harness, P0607, P0CC8, P1916, P1939, rub, short, U11FD, U164E, U1961, voltage, warning, wear, worn

Warranty Information

Version	3
Modified	09/10/2024 - Created on. 12/03/2024 - Updated Correction. 08/06/25- Updated correction to add one pedal drive disabled, additional codes and keywords.

