

Field Action Number	653.20
Release notes	<p>GM Update 653.20 Fixes occasional rear camera display issues when shifting to reverse</p> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
Model Year	2024
Make	Buick
Model	Envision
Components	VCU (Vehicle Cockpit Unit)