

Field Action Number	624.30
Release notes	<p>Software Update GM 624.30</p> <ul style="list-style-type: none"> • Improves frunk latching performance in cold temperatures. • Improves fuel range accuracy in shuttle mode • Improves Check Engine Light accuracy • Improves center display adjustment to ambient lighting changes. • Improves warnings when a key is missing. • Improves tuning for interior lighting in Stealth mode. • Improves automatic low beam headlamp logic. • Improves AWD notifications. <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
Model Year	2024
Make	Chevrolet
Model	Corvette
Components	<p>BCM (Body Control Module) BSM (Bi-directional Switching Module) ECM (Engine Control Module) ICCM (Integrated Chassis Control Module) IPC (Instrumented Panel Cluster) PFCM (Power Front Closure Module) TCM (Transmission Control Module)</p>