

Sarah Atchison

From: Brett Jensen
Sent: Tuesday, September 2, 2025 1:40 PM
To: Sarah Atchison
Subject: FW: Steering Wheel Air Horn Switch
Attachments: Air Horn Via Steering Wheel update.docx

Follow Up Flag: Follow up
Flag Status: Flagged

See below air horn email

Brett Jensen
VP/General Manager

My intent is to listen to my customers,
determine their wants and needs, configure
an apparatus that will be maintenance
friendly, built with excellence in workmanship,
cost effective, and most importantly, safe for the
men and women that serve their communities.

Midwest Fire Equipment & Repair Co.

Direct: 1-507-690-2981
Office: 1-800-344-2059
Office: 1-507-283-9141
Email: brett@midwestfire.com
Fax: 1-507-283-9142
Web: www.MidwestFire.com

NOTICE: This communication, including attachments, is for the intended recipient only. It may contain confidential or proprietary information. Unauthorized use, disclosure, or copying is prohibited and may be illegal. If you received this by mistake, please inform the sender and delete it permanently. **Confirm all payment instructions &/or requests verbally before proceeding with payment.**

Subject: Steering Wheel Air Horn Switch

Good Morning Everyone,

Attached are the updates that need to be made to your Freightliner chassis for the air horn button on the steering wheel.

You will need to take your truck to the local Freightliner authorized service center for this update. The update will be covered under warranty.

If you have any questions or issues having this completed, please don't hesitate to give me a call.

Thank you

Brett Jensen

VP/General Manager

My intent is to listen to my customers, determine their wants and needs, configure an apparatus that will be maintenance friendly, built with excellence in workmanship, cost effective, and most importantly, safe for the men and women that serve their communities.

Midwest Fire Equipment & Repair Co.

Direct: 1-507-690-2981

Office: 1-800-344-2059

Office: 1-507-283-9141

Email: brett@midwestfire.com

Fax: 1-507-283-9142

Web: www.MidwestFire.com

NOTICE: This communication, including attachments, is for the intended recipient only. It may contain confidential or proprietary information. Unauthorized use, disclosure, or copying is prohibited and may be illegal. If you received this by mistake, please inform the sender and delete it permanently. **Confirm all payment instructions &/or requests verbally before proceeding with payment.**

XMC Horn Logic Update for Air Horn via Steering Wheel

Connect to Parameters

- Go to XMC02T
 - Locate Parameter Domain "FSC Logic Block 16_20" and expand
 - Locate "PFSC_logic_blk0019_in1_sel"
 - Change to A0374479146-FlexibleCANEvent0001
 - Locate PFSC_logic_blk0019_in2_sel"
 - Change to A0374479246-Horn_Switch_Req
 - Locate "Supplementary Horn Controls" and expand
 - Locate "PFSC_Svcout_FootSwitch_sel"
 - Change to A0374479046-Logic_Block0019_result

CLICK SEND TO SAVE THE PARAMETER UPDATES

ONCE UPDATE IS COMPLETE

DISCONNECT FROM DIAGNOSTIC LINK

ENSURE THE DASH SWITCH FOR THE AIR HORN SELECTOR IS SET PROPERLY

CHECK TO MAKE SURE AIR HORN WORKS ON STEERING WHEEL BUTTON