

## PHEV GEN4 INVERTER MISSING COVER SERIAL NUMBER INSPECTION AND HANDLING GUIDANCE

### Technician Voice:

- Plastic protective dust cover is missing on the replacement part.

### Technical Description:

- JLR Engineering has confirmed units without the cover are still suitable for use.
- Proper handling during installation is critical to avoid damage or contamination.

### Status:

- Inspect the EPIC unit before installation
- If the plastic cover is missing, check the unit's serial number with the list on the SSM.
- If the serial number matches the approved list below, proceed with installation using the following precautions:
  - Handle only by the outer casing.
  - Avoid direct contact with the exposed Printed Circuit Board.

**Note:** If retailer has an inverter without the dust cover and serial number is not on the chart attached to the SSM, please raise an EPQR.

SSM 76373

### Range Rover

- 24-25MY Range Rover -PHEV
- 24-25MY RR Sport - PHEV

