



Service Bulletin

Bulletin No.: PIT6430

Date: August, 2025

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Rear HVAC Display Blank / Rear HVAC Inoperative

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Yukon	2025		All	All	All	All
GMC	Yukon XL	2025		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	GA4 (AT4 X) or GFY (Denali)
Condition	A customer may comment that the rear HVAC display is blank or that rear HVAC is not working. Technician may find DTC B1D77 SYM87 setting.
Cause	There may be a loose connection on the LVDS cable at P16 Instrument Panel Cluster Control Module , X227L, or A34 Heater and Air Conditioning Auxiliary Control.

Correction

Check for all connectors being fully seated and CPA's being engaged.

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005.

Version	1
Modified	08/26/2025 – Created on.

