



# Service Bulletin

Bulletin No.: 25-NA-114

Date: May, 2025

## INFORMATION

**Subject: Anti-Chip Coating Appearance**

**This Bulletin replaces PIT5650B. Please discard PIT5650B.**

| Brand:    | Model:                                                | Model Year: |      | VIN: |    | Engine: | Transmission : |
|-----------|-------------------------------------------------------|-------------|------|------|----|---------|----------------|
|           |                                                       | from        | to   | from | to |         |                |
| Chevrolet | Silverado 1500                                        | 2018        | 2025 | -    | -  | All     | All            |
|           | Silverado 1500 LTD<br>(RPO J21, VIN Digit 5 = W / Y)  | 2022        | 2022 |      |    |         |                |
|           | Silverado 1500 New<br>(RPO J22, VIN Digit 5 = A / D)  | 2022        | 2022 |      |    |         |                |
|           | Silverado 2500HD/<br>3500HD                           | 2019        | 2025 |      |    |         |                |
| GMC       | Sierra 1500                                           | 2018        | 2025 |      |    |         |                |
|           | Sierra 1500 Limited<br>(RPO J21, VIN Digit 5 = 8 / 9) | 2022        | 2022 |      |    |         |                |
|           | Sierra 1500 New<br>(RPO J22, VIN Digit 5 = H / U)     | 2022        | 2022 |      |    |         |                |
|           | Sierra 2500HD/<br>3500HD                              | 2019        | 2025 |      |    |         |                |

|                                   |                                                                                                                                                                                                                                                                                                                                                                                                                  |
|-----------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Involved Region or Country</b> | North America                                                                                                                                                                                                                                                                                                                                                                                                    |
| <b>Additional Options (RPOs)</b>  | Built at Oshawa Assembly Plant (11th VIN position "1")                                                                                                                                                                                                                                                                                                                                                           |
| <b>Condition</b>                  | A customer may ask about the lack of anti-chip coating on the lower painted surfaces of the exterior for trucks built at Oshawa.                                                                                                                                                                                                                                                                                 |
| <b>Cause</b>                      | Please be advised that trucks built at Oshawa assembly utilize a powder anti-chip material process for stone guard protection, which does not have a textured appearance. The anti-chip performance meets all engineering criteria for durability and quality without a visibly textured surface.<br>Trucks built at Flint, Fort Wayne, and Silao will have a textured appearance to the stone guard protection. |
| <b>Correction</b>                 | No repairs should be performed.                                                                                                                                                                                                                                                                                                                                                                                  |

**Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**

|          |                       |
|----------|-----------------------|
| Version  | 1                     |
| Modified | Released May 07, 2025 |

