



Service Bulletin

Bulletin No.: PIE0806B

Date: May, 2025

ENGINEERING INFORMATION

Subject: Engineering Information - (EI Lite) (Picture Only) Rocker Moldings Experiencing Poor Fit, Loose Parts, Broken Clips and/or Warp

This PI has been revised to end the need for gathering information from the field. Please discard PIE0806A.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2023	2024	—	—	—	—
Chevrolet	Suburban						
	Tahoe						
GMC	Yukon Models						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released October 22, 2024 Revised February 26, 2025 — Added 2025 Model Year. Revised May 07, 2025 - Ended the need for gathering further information from the field.

