

Circular Letter

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

Quattroporte Upper Dashboard Panel Serviceability



DATE: September 8, 2025

This bulletin provides updated guidance regarding the serviceability of the upper dashboard panel on Maserati Quattroporte vehicles. Beginning with Model Year 2016, it is possible to replace only the upper dashboard panel rather than the complete dashboard assembly. **REPLACE THE UPPER DASHBOARD PANEL ONLY IF, the affected area is not repairable per bulletin "MAS004616 MTB 25-07 Ghibli QP Levante Dashboard Leather Repair Procedure".**

MODELS AFFECTED: Quattroporte M156 (ALL MODEL YEARS)

Condition

On some Quattroporte vehicles, the leather on the upper dashboard panel may show signs of lifting or separation in the central area.

- When this condition is assessed as **"non-reworkable"** (per MAS004616 or later revisions), dealers are now authorized to replace only the upper dashboard panel instead of the complete dashboard assembly. **DO NOT replace the upper dashboard if the area affected is reworkable!**
- This update provides a more efficient and cost-effective service option, while ensuring vehicles continue to meet Maserati quality standards.



