

Customer Notification

Corporate Compliance
Po Box 30
MIDDLEBURY, INDIANA 46540-9218



INTERIM DEALER NOTIFICATION

A SECONDARY NOTICE WILL FOLLOW
WHEN THE REMEDY IS AVAILABLE

FOREST RIVER ID: 51-1958
FORD RECALL: 25S75 / 25V455

<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- o Integrity
- o Safety
- o Quality
- o Customer Service

September 2025

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

–Forest River motorized and towable products are contained in this section–

Dear Forest River Customer:

Forest River is alerting you to a Ford recall 25S75 / 25V455 involving certain 2021-2024 Rockport Work Trucks. Please see the information below which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

On your vehicle, it is possible to have a loss of fuel pressure and flow from the fuel tank due to fuel pump failure. This can cause a lack of fuel delivery to the engine and result in an engine stall while driving. Prior to fuel pump failure, you may experience poor engine performance (misfiring or running rough), a check engine light, or a reduction in engine power. Fuel pump failure is more likely to occur under low fuel or warm weather and hot fuel conditions in the fuel tank. An engine stall while driving increases the risk of a crash.

OWNERS AND DEALERS: WHAT SHOULD YOU DO?

Please review and follow the notice that accompanies this letter.

Sincerely,

Forest River Inc.
Office of Corporate Compliance



Ford Motor Company
Customer Service Division
PO Box 1904
Dearborn, Michigan 48121



771327672636

A/1/000012/1



July 2025

JOHN A. SAMPLE
123 SAMPLE ST
SAMPLE CITY, MI 12345-6789

***** IMPORTANT SAFETY RECALL *****

Safety Recall Notice 25S75 / NHTSA Recall 25V455

This Notice Applies to Your Vehicle, Vehicle Identification Number (VIN): [REDACTED]

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2022 Expedition, certain 2021-2022 F-150 and Mustang vehicles, and certain 2021-2023 Model Year Bronco, Explorer, and Super Duty vehicles (which includes F-250, F-350, F-450, F-550, and F-600), including the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue? On your vehicle, it is possible to have a loss of fuel pressure and flow from the fuel tank due to fuel pump failure. This can cause a lack of fuel delivery to the engine and result in an engine stall while driving. Prior to fuel pump failure, you may experience poor engine performance (misfiring or running rough), a check engine light, or a reduction in engine power. Fuel pump failure is more likely to occur under low fuel or warm weather and hot fuel conditions in the fuel tank.

What is the risk? An engine stall while driving increases the risk of a crash.

What will Ford and your dealer do? A remedy is not yet available. Ford Motor Company is still actively investigating this issue and working to develop a remedy. When the remedy becomes available, Ford Motor Company will notify you via mail to schedule a service appointment with your dealer for repairs to be completed free of charge.

What should you do? When the remedy is available, Ford Motor Company will send a letter to inform you to contact your dealer to schedule a repair. Ford has not issued instructions to stop driving your vehicle under this safety recall. When the remedy is available, you should contact your dealer for an appointment to have your vehicle remedied as soon as practicable.

**What should you do?
(continued)**

If you do not already have a servicing dealer, you can access ford.com/support for dealer addresses, maps, and driving instructions.

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-275-9171) or go to [NHTSA.gov](https://www.nhtsa.gov). Reference NHTSA Safety Recall 25V455.

Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

NOTE: You can receive information about Recalls and Customer Satisfaction Programs through our FordPass App. The app can be downloaded through the App Store or Google Play. In addition, there are other features such as reserving parking in certain locations and controlling certain functions on your vehicle (lock or unlock doors, remote start) if it is equipped to allow control.

What if you no longer own this vehicle?

If you no longer own this vehicle and have an address for the current owner, please forward this letter to the new owner.

You received this notice because government regulations require that notification be sent to the last known owner of record. Our records are based primarily on state registration and title data, which indicate that you are the current owner.

Thank you for your attention to this important matter.

Customer Service Division

Customer Notification

Corporate Compliance
Po Box 30
MIDDLEBURY, INDIANA 46540-9218



FOREST RIVER

INTERIM OWNER NOTIFICATION

A SECONDARY NOTICE WILL FOLLOW
WHEN THE REMEDY IS AVAILABLE

FOREST RIVER ID: 51-1958
FORD RECALL: 25S75 / 25V455

<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- o *Integrity*
- o *Safety*
- o *Quality*
- o *Customer Service*

September 2025

Dear Forest River Customer:

Forest River is alerting you to a Ford recall 25S75 / 25V455 involving certain 2021-2024 Rockport Work Trucks. Please see the information below which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

On your vehicle, it is possible to have a loss of fuel pressure and flow from the fuel tank due to fuel pump failure. This can cause a lack of fuel delivery to the engine and result in an engine stall while driving. Prior to fuel pump failure, you may experience poor engine performance (misfiring or running rough), a check engine light, or a reduction in engine power. Fuel pump failure is more likely to occur under low fuel or warm weather and hot fuel conditions in the fuel tank. An engine stall while driving increases the risk of a crash.

OWNERS AND DEALERS: WHAT SHOULD YOU DO?

Please review and follow the notice that accompanies this letter.

Sincerely,

Forest River Inc.
Office of Corporate Compliance