



VEHICLE - WARRANTY BULLETIN

Can-Am On-Road

SEPTEMBER 25, 2025

BULLETIN 2025-7 | VERSION A

CAMPAIGN N° 2025-0007

! CAUTION

All involved customers must be notified, all involved units must be corrected as per instruction herein.

Origin Rear Central Reflector Replacement

IMPORTANT

When receiving a vehicle for service:

- Always lookup the vehicle identification number (VIN) on the Knowledge Center to check for pending campaigns or alerts.
- Always connect the vehicle to the BRP diagnostic software (BUDS) to ensure all required updates are performed.

APPLICABILITY

MODEL YEAR	MODEL	ADMISSIBLE UNITS
MY25	Can-Am Origin	Go to BOSSWeb/Warranty/Campaign Monitoring to know which units in your inventory are impacted by this campaign.

PROBLEM

The rear reflector adhesion may not be optimal.

SOLUTION

At PDI, inspect the rear reflector. Replace it if necessary.

REQUIRED PARTS

Order the parts through the regular channel.

DESCRIPTION	PART NUMBER	QTY
Rear red reflector	705015551	1




CORRECTIVE ACTION

Inspection Procedure


Try to gently lift the side of the reflector with your fingers. If it is firmly bonded with the surface, do not replace it. If it is partially unglued and easy to lift, proceed with the *Repair Procedure*.

Repair Procedure


- 1. Remove and discard the rear reflector from the vehicle.



- 2. Clean the surface to eliminate all glue residues, dust and grease.
- 3. Peel off the protective liner from the new reflector.
- 4. Align and firmly install the new reflector. Apply strong pressure (150 N) with both thumbs, placed at one quarter of each side of the reflector, for 30 seconds.



- 5. Apply strong pressure (150 N) at the center of the reflector, for 30 seconds.



NOTE

150 N = force applied by pressing firmly with both thumbs, similar to supporting a 15 kg / 33lb weight

WARRANTY

Submit a warranty claim using the following information.
For claiming procedure, refer to the online *Dealer/Distributor Warranty Guide*.

INSPECTION ONLY

WITH BOSSWEB

CLAIM DETAILS	
Product Line	Motorcycle
Unit Model Year	2025
Campaign/Bulletin/Description	7 / 2025-7 / Rear Reflector
*Action InspectRepair ☒☐	



CLAIM DETAILS	
Total Labor Time Paid	0.1 hour
Expiration Date	October 31, 2028

WITH WARRANTY ON DEMAND

CLAIM DETAILS	
Claim Type	Unit Campaign
Serial Number	Enter Serial Number
Warranty Campaign	Select 2025 - Rear Reflector / BULLETIN 2025-7 / 2WV-2025-0007 from the drop-down list
Date of Repair	Repair date
Total Labor Time Paid	0.1 hour
Expiration Date	October 31, 2028

INSPECTION AND REPAIR

WITH BOSSWEB

CLAIM DETAILS	
Product Line	Motorcycle
Unit Model Year	2025
Campaign/Bulletin/Description	7 / 2025-7 / Rear Reflector
*Action Inspect ☒ Repair ☒	
Total Labor Time Paid	0.2 hour
Expiration Date	October 31, 2028

WITH WARRANTY ON DEMAND

CLAIM DETAILS	
Claim Type	Unit Campaign
Serial Number	Enter Serial Number
Warranty Campaign	Select 2025 - Rear Reflector / BULLETIN 2025-7 / 2WV-2025-0007 from the drop-down list
Date of Repair	Repair date
Total Labor Time Paid	0.2 hour
Expiration Date	October 31, 2028