

<b>Update Title</b>	GM Update 653.30
<b>Associated Field Action Number(s)</b>	N25-251041
<b>Release notes</b>	<p>This software update includes the following, if your vehicle is equipped:</p> <ul style="list-style-type: none"> <li>• Improvements to the rear view camera.</li> <li>• Fixes to address missing trailer indicators</li> <li>• Fixes to front and rear display responsiveness</li> <li>• Improvements to performance of climate controls</li> <li>• Additional improvements and fixes implemented</li> </ul> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
<b>Model Year</b>	2024
<b>Make</b>	Brightdrop
<b>Model</b>	Zevo 400
<b>Components</b>	VCU (Vehicle Cockpit Unit)