

Update Title	GM Update 653.30
Associated Field Action Number(s)	N25-250322
Release notes	• Improvements to the rear view camera. • Fixes to address missing trailer indicators. • Fixes to display responsiveness. • Improvements to performance of climate controls. • Fixes to Universal Remote reset. During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.
Model Year	2025
Make	Chevrolet
Model	Equinox EV
Components	VCU (Vehicle Cockpit Unit)