

 Preview Solution CBR-2505-1

Mack Chassis - Eco Roll Disable Switch Inop - PR (4)

Published 22 September 2025

Vaild For

Mack Chassis - PR (4)

Model Year - 2025 to current

The purpose of this CBR is to address the issue with Eco Roll disable switch not working.

Overview

Mack Trucks has identified an issue with the Eco Roll disable switch. The switch is currently operating in reverse. When the switch is pressed and illuminated, Eco Roll becomes active. When the switch is not illuminated, Eco Roll is disabled.

This is a software issue, and a fix will be released at a later date. In the meantime, please do not diagnose this concern. Instead, inform customers how to operate the switch as outlined above until the software update becomes available.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article