

Technical Journal

TITLE:

Wind noise front side window

REF NO: TJ 37336.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2025-08-18	STATUS DATE: 2025-09-23
FUNC GROUP: 8441	FUNC DESC: Glass for front side door	Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If customer complains of wind noise coming from the front side window, follow advice under "Service".

*Updated VST Op number

CSC Customer Symptom Codes

Code	Description
H6	Doors/Wind noise/Around front side door/window

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
814							2024-9999		-	202346-999952

SERVICE:

Before replacing any parts, follow the checklist below.

1. Check the calibration of the window. If needed, recalibrate the window.
2. If that doesn't solve the issue, check the triangular trim panel on front door for any gap or deformation. If there is damage or deformation, replace the part.

Technical Journal 37336.2.0

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
99923-2	General reimbursement acc. to TJ
85120-2	Door panel, front removal

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 8441.