

WSJ1 Workshop Campaign – Replacing electric closing aid for lid

WSJ1 Workshop Campaign - Replacing electric closing aid for lid

ID Number	WSJ1
Model(s)	Macan (XAB)
Model Year(s)	2024 - 2026
VIN List	Attached
Number of Affected VINs	198
Issue Description	On the affected vehicles, electric closing aids for the rear lid were installed with improperly installed micro-switches for determining the lid position. Due to the faulty signal from the microswitch, the rear lid cannot be opened, closed or locked, and the message "Doors open" is displayed on the instrument cluster. To prevent this, the engine closing aid on the rear lid needs to be replaced by an optimized version on the affected vehicles.
What Porsche Centers Should Do	Please arrange for this action to be carried out on the affected vehicles during the next workshop visit or before the vehicles are handed over to customers. (Solution available as of 09/15/2025)
TI	WSJ1
Part Status	Status 1 - Order as needed

Required parts

The required parts for carrying out the campaign can be found in the respective Technical Information (TI), "Warranty Processing" section.

Warranty processing

Validity:

WSJ1 Workshop Campaign – Replacing electric closing aid for lid

This workshop campaign will be carried out up to 04/09/2030 and will be closed on the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WSJ1 66 000
Repair Code	2
Labor time	51 TU

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service again via WWS with the campaign scope

Attachments

1. [WSJ1 Workshop Campaign VIN list for Field Managers V3 09.15.2025 HT.xlsx](#)