

Bulletin #: C32-0925-0650		☐ Take Note ☒ Take Action	
☐ Retail Operator	☐ Sales Pre-Owned	☐ Business Manager	☒ Parts & Accessories
☐ General Manager	☐ Sales New Car	☐ Service	☐ Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: September 22, 2025		Supersedes:	



BMW PARTS BULLETIN

TEC792 REAR AXEL RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

33 10 8 881 536

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing oil accumulation in the plastic bag of the packaging.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC792 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC792 is valid from September 22, 2025, through October 06, 2025. The deadline for filing a claim under TEC792 is October 06, 2025. All parts must be returned to your facing RDC no later than October 20, 2025.

Please reorder the same part number as needed.

Affected Parts (NOT OK)	Non Affected Parts (OK)
All parts with oil accumulation in the plastic bag of the packaging	
more Information	
There are no pictures - just a note:	
If oil has accumulated in the plastic bag, the part must be scrapped. There is a risk that oil has leaked out via the vent valve.	
There are no reworking or inspection instructions. The HAG is too heavy, cannot be lifted out and must not be turned, otherwise oil will also leak out of the oil filler supports.	