



Service Bulletin

Bulletin No.: PIP6045B

Date: October, 2025

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: Chirp Noise Heard From Inside Engine Compartment

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2025 - 2026		All	All	2.5 LK0	All
Chevrolet	Traverse	2024 - 2026		All	All	2.5 LK0	All
GMC	Acadia	2024 - 2026		All	All	2.5 LK0	All

Involved Region or Country	North America
Condition	Chirp noise heard from engine compartment
Cause	Engineering currently investigating root cause

Correction

If you encounter a chirp type noise coming that is coming from inside the engine do not attempt any repairs at this time as Engineering is currently investigating the root cause of the condition.

Note: This noise may be intermittent in nature and is not temperature dependent. Reference audio file below for chirp noise.

SEE Service Information or attached video below

Version	3
Modified	02/14/2025 - Created on. 07/10/2025- Updated Model Year. 10/10/2025- Updated to remove unique labor operation

