



STAR ONLINE PUBLICATION



Case Number: S2523000085

Release Date: October 2025

Symptom/Vehicle Issue: LED Fog Lamp Inoperative.

Customer Complaint/Technician Observation: Condition may occur after a recent repair involving front lighting/modules. Technician may not find any diagnostic trouble codes (DTC). One or both LED fog lamp(s) may not work.

Discussion: To validate the condition, perform the following:

1. Turn the car ignition ON and release park brake.
2. Set the headlight switch to the ON or AUTO position, then turn on the fog lamps.
3. Both fog lamps must be turned on.

If the fog lamp(s) do not light, perform Restore Configuration first with wiTECH. Then perform Proxi Configuration Alignment. The purpose of this is to make sure the vehicle has the correct configuration learned and then send the configuration to all the modules (or align the modules).

Verification:

1. Turn the car ignition ON and release park brake.
2. Set the headlight switch to the ON or AUTO position, then turn on the fog lamps. Both lamps should light.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.