

Update Title	GM Update 653.40
Associated Field Action Number(s)	N25-251057
Release notes	<ul style="list-style-type: none"> • Fixes occasional rear camera display issues when shifting to reverse • Improves HVAC optimization for remote start performance <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
Model Year	2024
Make	Chevrolet GMC
Model	Canyon Crew Cab Colorado Crew Cab
Components	VCU (Virtual Cockpit Unit)