

<b>Update Title</b>	GM Update 653.31
<b>Associated Field Action Number(s)</b>	N25-251815
<b>Release notes</b>	<p>Fixes to help ensure safety features remain functional when windshield freezes.</p> <p>Fixes to diagnostics that impact Automatic Emergency Braking indicator.</p> <p>Fixes to help protect battery life.</p> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
<b>Model Year</b>	2024
<b>Make</b>	GMC
<b>Model</b>	Canyon
<b>Components</b>	FCM (Front Camera Module)