

Update Title	GM Update 653.20
Associated Field Action Number(s)	N25-249763 N25-250020 N23-242884 N25-250403 N25-249569 N25-250179 N25-250344
Release notes	<ul style="list-style-type: none"> • Improves how center display adjusts to lighting changes. • Improved warnings when a key is missing. • Better tuning for interior lighting in Stealth mode. • Improvements to automatic low beam headlamp logic. • Smoother dimming and transitions from day to night. • Improves Check Engine Light accuracy. • Improves behavior of aero shutter system in freezing temperatures. • Fixes to help prevent erroneous collision calls. • Fixes to address issues with OnStar stolen vehicle responses. • Improvements to performance of software updates and connectivity. • Fixes to help prevent battery drain. • Fixes to responsiveness issues with Wi-Fi, Navigation, Super Cruise, and OnStar. • Improvements to software updates. • Improvements to OnStar emergency calls. • Fixes to address cellular connectivity issues. • Fixes calculation of vehicle brake pad life to address inaccurate status shown on center display. <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation. If you are not using your vehicle's built-in 4G</p>

	LTE connection, then applicable data rates apply.
Model Year	2025
Make	Buick Chevrolet GMC
Model	Acadia Traverse
Components	ACP (ADAS Compute Platform) BCM (Body Control Module) CGM (Communication Gateway Module) EBCM (Electronic Brake Control Module) PCM (Powertrain Control Module) TCP (Telematics Communication Platform)