

Bulletin #: C32-1025-0655		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: October 13, 2025		Supersedes:	



# BMW PARTS BULLETIN

## TEC797 GASKET SET RETURN

### TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

11 42 9 888 806

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing unknown design, incorrect composition shown in image below (left). Parts shown on the right are ok for use.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC797 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC797 is valid from October 13, 2025, through October 27, 2025. The deadline for filing a claim under TEC797 is October 27, 2025. All parts must be returned to your facing RDC no later than November 10, 2025.

Please reorder the same part number as needed.

