



Technical Service Bulletin

GROUP	NUMBER
CAMPAIGN	25-01-078G
DATE	MODEL(S)
OCTOBER 2025	GV70 (JK1, JK1A)

SUBJECT: FRONT BRAKE SQUEAL NOISE PAD REPLACEMENT
(LIMITED COVERAGE CAMPAIGN L01G)

★ IMPORTANT

This field action is to be performed on non-retailed Retailer stock vehicles only and must be completed prior to retail delivery to a guest.

Access the "Vehicle Information" screen via WebDCS to confirm the vehicle's applicability by verifying the "Retail Flag" field does not list "Y" under the 'Basic Vehicle Information' section.

Description: Certain GV70 (JK1, JK1A) vehicles may exhibit squeal noise during certain braking conditions. Follow the procedures in this bulletin to replace the front brake pads and radial springs to resolve the condition.



Applicable Vehicles (Certain):


Model Year	Model	Production Dates	VIN Prefix
2026	GV70 (JK1)	03/06/2025 – 10/21/2025	KMU
2026	GV70 (JK1A)	02/11/2025 – 10/21/2025	5NM

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

SUBJECT:

**FRONT BRAKE SQUEAL NOISE PAD REPLACEMENT
(LIMITED COVERAGE CAMPAIGN L01G)**

Parts Information:

Model	Part Name	Part Number	Figure
GV70 (JK1, JK1A)	Pad Kit – Front Disk Brake	58101-ARA16QQH	

SST Information:

Tool Name	Tool Number	Figure	Ordering Information
Piston Expander	09581-C3100		Website: https://genesisessentialtools.com/ Email: Genesisistools@snapon.com Phone: 1-855-763-6630 Hours: 7 AM – 7 PM CST

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
GV70 (JK1, JK1A)	50D278R1	Front Brake Pad Replacement (Both Sides)	0.5 M/H	58101-ARA10	Q42	ZZ1

NOTE 1: Submit claim on Claim Entry Screen as “Campaign” type.

NOTE 2: This field action is to be performed on non-retailed Retailer stock vehicles only and must be completed prior to retail delivery to a guest.

NOTE 3: If any part(s) not subject to this TSB are in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to the TSB are out of warranty coverage, the retailer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

NOTE 4: This TSB includes repair validation photos. Op times include VIN, mileage, and repair validation photo(s) as outlined in the Digital Documentation Policy.

NOTE 5: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

Service Procedure:**DIGITAL DOCUMENTATION**

This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.


NOTICE

Applying the recommended torque to all fasteners is essential to reduce potential issues from occurring after the service procedure.

1. Visually check if the lift blocks are properly seated on the vehicle support points and raise the vehicle.

NOTICE

When raising a vehicle from anywhere other than the support points may damage vehicle components.





Refer to the shop manual.

- **General Information > Lift and Support Points > General Information**

2. Remove both front brake pads (A) and radial spring (B) from both sides of the vehicle by referring to the shop manual:

- **Brake System > Brake System > Brake Pad > Removal**



SUBJECT:

**FRONT BRAKE SQUEAL NOISE PAD REPLACEMENT
(LIMITED COVERAGE CAMPAIGN L01G)**

3. Install the new radial spring and brake pads by referring to the shop manual:
 - **Brake System > Brake System > Brake Pad > Installation**

4.


**DIGITAL
DOCUMENTATION**



Using the STUI Camera function, take photos of the new brake pads installed on both sides of the vehicle.

Upload the photo to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and the date of repair on a piece of paper to include in the photo.



SUBJECT:**FRONT BRAKE SQUEAL NOISE PAD REPLACEMENT
(LIMITED COVERAGE CAMPAIGN L01G)**

5. Reassemble all parts in the reverse order of the removal process.
6. Check for brake fluid leaks and confirm proper pedal operation by performing a short road test.
7. The service procedure is now complete.