

Authored Date	03/10/2025	
Doc No.	IATSB004327	
Title	Handbrake Bezel Ring – Remove and Install	
Affected Vehicle(s)	Station Wagon QuarterMaster	PF00001 -
This Technical Service Bulletin (TSB) should only apply to vehicles that demonstrate the described issue below.		

Reason for this document

Issue: An issue has been identified where the handbrake bezel ring cracks.

Cause: This is due to the bezel being too thin.

Action: Follow the procedure below.

Workshop Procedure

Handbrake Bezel Ring

Operation:	SRO	Repair Time:
Handbrake Bezel – Remove and Install	XHBR0006428	0.2 Hours

Parts

Part Number	Description	Qty
GRA-6B00-051660	Handbrake Bezel Ring – Grey	1
GRA-6B00-051650	Handbrake Bezel Ring – Green	1
Local Supply	Super Glue All Plastics 2 GM – Loctite or similar.	1

Note:

- The procedure contains illustrations showing certain components removed to provide extra clarity.
- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.



Removal


1.

Open Driver's Door.

2.

Cautions


Take care not to damage surrounding components.



Using a suitable tool, remove the Handbrake Bezel Ring.

Installation

1.



- Place suitable glue on the 2 tabs on the new Handbrake Bezel Ring.
- Install the new Handbrake Bezel Ring.

Parts: GRA-6B00-051660 – Handbrake Bezel Ring – Grey. Quantity: 1

GRA-6B00-051650 – Handbrake Bezel Ring – Green. Quantity: 1

Local Supply - Super Glue All Plastics 2 GM – Loctite. Quantity: 1

2.

Close Driver's Door.

3.

Release vehicle.

Change History

Reference No.	Date	Description
IATSB004327	03/10/2025	First release