



# Service Bulletin

American Honda Motor Co., Inc.

C125 #1  
October 2025

## EMISSION RECALL

### 2019-2024 C125 SUPER CUB FUEL SYSTEM

#### BACKGROUND

Honda is launching an **EMISSION RECALL** on ALL 2019-2024 C125 Super Cub motorcycles. A fuel permeation test revealed that the fuel system does not meet regulatory standards. The fuel system has a lower than expected permeation value and is not within emission certification compliance.

#### AFFECTED UNITS

As of October 31, 2025, you **MUST NOT SELL ANY NEW or USED** 2019-2024 C125 Super Cub motorcycle until it is repaired according to a forthcoming Service Bulletin.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information* on **IN**, available on November 5, 2025.
- To manage your affected new inventory, use your dealer *eResponsibility Report* on **IN**, available on November 5, 2025.

#### CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected scooters in **December** 2025. Customers will be informed that their scooter is affected by this emissions-related defect. Once parts become available, customers will be notified by a second letter to make an appointment with an authorized Honda dealer for repair.

#### PARTS INFORMATION

The parts needed for the repair can be ordered according to the instructions in a forthcoming Service Bulletin.

#### SERVICE BULLETIN

This service bulletin (C125 #1) will be revised to include all parts and repair information relating to this Emissions Recall once parts become available. Dealers will be notified by **IN** message.

#### DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.